ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109

## **Defect Listing**

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
A8-4_	_A8-3	Oliver S	Springs	Main St	Concrete Pipe (non		Light High	Sanitary	
Upstream MH Total Length		Year Laid	Sh	Shape		Details			
A8	A8-4 210		6.1		Circ	cular			
DS Ma	anhole	Length s	urveyed	Year Renewed	Height	Height Width Pipe Joint			
A8	3-3	216.1			8	8	4		
SPR	N/A	MPR	N/A	PO Number			Customer		
0001	N1/A			4397-03		GRW			
SPRI	N/A	MPRI	N/A	Work Order		Purpose			
QSR	N/A	QMR	N/A	4397-02	Pre-Rehabilitation Su			urvey	
OF	PR	Survey	ved By	Direction	Date		Media label		
N/	<b>'</b> A	Barry_Rogers		Downstream	20150814				
OPRI		Certificate Number		Pre-Cleaning	Time		Weather		
N/	N/A U-1012-16405		Jetting	08:40		Dry			
		Date C	leaned		End Time		Additional Info		
		2015	0814	08:53					

Distance	Condition	Cont. Dfct.	Values			la:u4	Clock Position		Grade
Distance	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A8-4								
0.0 ft.	Water Level				15				
37.3 ft.	Tap Factory Made Active		6		0		2		
136.6 ft.	Water Level				20				
190.9 ft.	Tap Factory Made		6		0		3		
213.0 ft.	Water Level				15				
216.1 ft.	Access Point Manhole				0				
Remarks:	A8-3								





## **Image Report 4/Page**

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A8-4_A8-3	Oliver Springs	Main St	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A8-4	216.1		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
A8-3	216.1		8	8	4	,



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A8-4



Distance: 0.0 ft. Grade: 0


Condition: Water Level

Remarks: N/A



Distance: 37.3 ft. Grade: 0
Condition: Tap Factory Made Active

Remarks: N/A



Distance: 136.6 ft. Grade: 0

Condition: Water Level

Remarks: N/A

**ITpipes** 4921 Alexander Blvd Albuquerque, NM 505-341-0109



## Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A8-4_A8-3	Oliver Springs	Main St	lain St Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A8-4	216.1		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A8-3	216.1		8	8	4	



Distance: 190.9 ft. Grade:

Condition: Tap Factory Made


Remarks: N/A



Distance: 213.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 216.1 ft. Grade: 0 Condition:

Access Point Manhole

Remarks: A8-3



## **PACP Conditions**

Pipe Segme	ent Refere	Ci	ity	Street	Mat	erial	Location C	Sewer Use	
A8-4_	A8-4_A8-3		Springs	Main St	Concrete P	ipe (non	Light High	Sanitary	
Upstre	Upstream MH		Length	Year Laid	Shape		Location Details		
A	A8-4		6.1		Circular				
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint		
AA A	A8-3		6.1		8	8	4		
SPR	N/A	MPR	N/A	PO Number			Customer		
SPRI	N/A	MPRI	N/A	4397-03			<b>GRW</b> Purpose		
01111	1973	IVII TXI	1973	Work Order					
QSR	N/A	QMR	N/A	4397-02	Pre-		Rehabilitation Survey		
OF	PR .	Surveyed By		Direction	Date		Media label		
N/	N/A		Rogers	Downstream	20150814				
OF	OPRI		e Number	Pre-Cleaning	Time		Weather		
N/	N/A		2-16405	Jetting	08:40		Dry		
		Date C	leaned	End Time		Additional Info			
(		2015	0814	08:53					

		Structural Ratings			0	& M Ratin	gs	Combined Ratings		
Normal Defects	,	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
		4	0	0	4	0		4	0	0
	-	2	0	0	2	0	0	2	0	0
		3	0	0	3	0	0	3	0	0
	ŀ	4	0	0	4	0	0	4	0	0
	ŀ	5	0	0	5	0	0	5	0	0
		5	0	U		U	U			U
Continuous Defe	cts									
Code ID Lei	ngth									
		Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY		Pi	pe Rating	0	Pi	pe Rating	0	Overall Pi	pe Rating	0
		Structural Index		0	O&M Index		0	Overall Index		0
		Str. Qu	Str. Quick Rating 0000		O&M Quick Rating		0000	Ovrl. Quick Rating 0		0000