ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



## **Defect Listing**

Pipe Segment Refere		City		Street	Mat	erial	Location C	Sewer Use
B-17_B-16		Oliver Springs		Cemetery Rd	Fibreglass	Fibreglass Reinforc		Sanitary
Upstream MH		Total Length		Year Laid	Sh	Shape		Details
B-	B-17		4.6		Circ	ular		
DS Ma	anhole	Length s	Length surveyed Year Renewed Height Width Pipe Join		Pipe Joint			
B-16		254.6			8	8	N/A	
SPR	N/A	MPR	N/A	PO Number	PO Number		Customer	
0001	-			4397-03		GRW		
SPRI	N/A	MPRI	N/A	Work Order			Purpose	
QSR	N/A	QMR	N/A	4397-02		Pre-Rehabilitation Survey		
Ol	PR	Surveyed By		Direction	Date		Media label	
N	/A	Charlie_Gordon		Downstream	20150910			
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather	
N/A		U-615-07000491		Jetting	10:02		Light Rain	
		Date C	leaned	End Time		Additional Info		
		2015	10:16					

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
Distance	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	B-17			•					
0.0 ft.	Water Level				5				
88.9 ft.	Lining Failure Other				0		9		
Remarks:	CUT								
180.0 ft.	Tap Factory Made		6		0		3		
222.7 ft.	Tap Factory Made		6		0		9		
253.3 ft.	Water Level				5				
254.6 ft.	Access Point Manhole				0				
Remarks:	B-16								





## **Image Report 4/Page**

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
B-17_B-16	Oliver Springs	Cemetery Rd	Fibreglass Reinforc		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
B-17	254.6		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
B-16	254.6		8	8	N/A	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: B-17



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 88.9 ft. Grade: 0

Condition: Lining Failure Other

Remarks: CUT



Distance: 180.0 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A





## Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
B-17_B-16	Oliver Springs	Cemetery Rd	Fibreglass Reinforc		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
B-17	254.6		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
B-16	254.6		8	8	N/A	ر ا



Distance: 222.7 ft. Grade:

Condition: Tap Factory Made

Remarks: N/A



Distance: 253.3 ft. Grade:

Condition: Water Level

Remarks: N/A



Grade: Distance: 254.6 ft. Condition:

Access Point Manhole

Remarks: B-16



## **PACP Conditions**

Pipe Segme	Pipe Segment Refere		ity	Street	Mat	erial	Location C	Sewer Use
B-17_	B-17_B-16		Springs	Cemetery Rd	Fibreglass Reinforc		Easement/R	Sanitary
Upstre	Upstream MH		Length	Year Laid	Shape		Location Details	
B-	B-17		4.6		Circ	ular		
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint	
В-	B-16		4.6		8	8	N/A	
SPR	N/A	MPR	N/A	PO Number			Customer	
SPRI	N/A	MPRI	N/A	4397-03			GRW	
01111	-	WII TO		Work Order			Purpose	
QSR	N/A	QMR	N/A	4397-02	Pre-		Rehabilitation Survey	
OF	PR	Surveyed By		Direction	Date		Media label	
N/	/A	Charlie_Gordon		Downstream	20150910			
OF	OPRI		e Number	Pre-Cleaning	Time		Weather	
N/	N/A		7000491	Jetting	10:02		Light Rain	
		Date C	leaned	End Time		Additional Info		
l		2015	0910	10:16				

	Stru	Structural Ratings			& M Ratin	gs	Con	nbined Ra	tings
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
	4			4		_	4		
	2	0	0	2	0	0	2	0	0
		0	0		0	0	3	0	0
	3	0	0	3	0	0		0	0
	4	0	0	4	0	0	4	0	0
	5	0	0	5	0	0	5	0	0
Continuous Defects									
Code ID Lengt	n								
	7								
	-								
	Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY	Р	ipe Rating	0	Pi	ipe Rating	0	Overall Pi	pe Rating	0
SOMMAN		ural Index		O&M Index		0	Overall Index		0
	Str. Qu	ick Rating	0000	O&M Quick Rating		0000			0000