

Defect Listing

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
B-18_	_B-17	Oliver	Springs	Cemtery Rd	Fibreglass	Reinforc Light High S		Sanitary	
Upstream MH		Total Length		Year Laid	Sh	Shape		Details	
B-	18	35	57		Circ	Circular			
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width Pipe Joint			
B-	17	35	57		8	8	N/A		
SPR	N/A	MPR	N/A	PO Number 4397-03			Customer		
0001		MDDI	-			GRW			
SPRI	N/A	MPRI	N/A	Work Order					
QSR	N/A	QMR	N/A	4397-02		Pre-Rehabilitation Su		urvey	
O	PR	Surve	ed By	Direction Date		ate Media label			
N	/A	Charlie_Gordon		Downstream	2015	20150910			
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
N	N/A		7000491	Jetting	09:14		Heavy Rain		
		Date C	leaned		End Time Addi		Additio	nal Info	
		2015	0910		09	:14			

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
Distance	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	B-18	•							
0.0 ft.	Water Level				10				
12.3 ft.	Tap Factory Made		6		0		3		
158.8 ft.	Tap Factory Made Active		6		0		9		
355.4 ft.	Water Level				5				
357.0 ft.	Access Point Manhole				0				
Remarks:	B-17								





Image Report 4/Page


Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
B-18_B-17	Oliver Springs	Cemtery Rd	Fibreglass Reinforc		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
B-18	357		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
B-17	357		8	8	N/A	,



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: B-18



Distance: 0.0 ft. Grade: (

Condition: Water Level

Remarks: N/A



Distance: 12.3 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 158.8 ft. Grade: 0

Condition: Tap Factory Made Active

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
B-18_B-17	Oliver Springs	Cemtery Rd	Fibreglass Reinforc		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
B-18	357		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
B-17	357		8	8	N/A	,



Distance: 355.4 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 357.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: B-17



PACP Conditions

Pipe Segment Refere		City		Street	Mat	terial	Location C	Sewer Use	
B-18_	_B-17	Oliver	Springs	Cemtery Rd	Fibreglass	Reinforc	Light High	Sanitary	
Upstrea	am MH	Total I	_ength	Year Laid	Sh	ape	De Location Details		
B-	18	35	57		Circ	Circular			
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width Pipe Joint			
B-	17	35	57		8	8	8 N/A		
SPR	N/A	MPR	N/A	PO Number	r		Customer		
SPRI	N/A	MPRI	N/A	4397-03					
JEKI	IN/A	IVIFIXI	IVA	Work Order					
QSR	N/A	QMR	N/A	4397-02		Pre-l	-Rehabilitation Survey		
OF	PR .	Surve	yed By	Direction	D	ate	Media	label	
N/	N/A Charlie_Gordon		Gordon	Downstream	2015	50910			
OF	OPRI		e Number	Pre-Cleaning	Time		Weather		
N/	N/A U-615-07000491		Jetting	09:14		Heavy Rain			
	Date Cleaned					End Time		nal Info	
		2015	0910	09	:14				

			Structural Ratings			0	& M Ratin	gs	Con	nbined Ra	tings
Normal Defects		Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	
			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code	ID	Length									
			Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY			pe Rating ural Index			pe Rating &M Index	0 0		ipe Rating erall Index	0 0	
			Str. Qu	ick Rating	0000	O&M Qui	ick Rating	0000	Ovrl. Quick Rating		0000