



Defect Listing

Pipe Segment Refere... B-2_B-1	City Oliver Springs	Street Old Harriman hwy	Material Fibreglass Reinforc...	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH B-2	Total Length 319.3	Year Laid	Shape Circular	Location Details	
DS Manhole B-1	Length surveyed 319.3	Year Renewed	Height 10	Width 10	Pipe Joint... N/A


SPR N/A	MPR 4	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI 2	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR 2200				
OPR 4	Surveyed By Charlie Gordon	Direction Downstream	Date 20150916	Media label	
OPRI 2	Certificate Number U-615-07000491	Pre-Cleaning No Pre-Cleaning	Time 08:12	Weather Dry	
Date Cleaned			End Time 08:31	Additional Info Liner through mh B-...	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: B-2									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
141.4 ft.	Deposits Attached Grease				5	<input type="checkbox"/>	7	9	2
161.8 ft.	Deposits Attached Grease				0	<input type="checkbox"/>	8		2
319.3 ft.	Water Level				5	<input type="checkbox"/>			
319.3 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: B-1									



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
B-2 B-1	Oliver Springs	Old Harriman hwy	Fibreglass Reinforc...	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
B-2	319.3		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
B-1	319.3		10	10	N/A



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: B-2



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 141.4 ft. Grade: 2
Condition: Deposits Attached Grease
Remarks: N/A



Distance: 161.8 ft. Grade: 2
Condition: Deposits Attached Grease
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere... B-2_B-1	City Oliver Springs	Street Old Harriman hwy	Material Fibreglass Reinforc...		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH B-2	Total Length 319.3	Year Laid	Shape Circular		Location Details	
DS Manhole B-1	Length surveyed 319.3	Year Renewed	Height 10	Width 10	Pipe Joint...	N/A



Distance: 319.3 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 319.3 ft. Grade: 0
Condition: Access Point Manhole
Remarks: B-1



PACP Conditions

Pipe Segment Refere... B-2_B-1	City Oliver Springs	Street Old Harriman hwy	Material Fibreglass Reinforc...	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH B-2	Total Length 319.3	Year Laid	Shape Circular	Location Details	
DS Manhole B-1	Length surveyed 319.3	Year Renewed	Height 10	Width 10	Pipe Joint... N/A
SPR N/A	MPR 4	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI 2	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR 2200				
OPR 4	Surveyed By Charlie Gordon	Direction Downstream	Date 20150916	Media label	
OPRI 2	Certificate Number U-615-07000491	Pre-Cleaning No Pre-Cleaning	Time 08:12	Weather Dry	
Date Cleaned			End Time 08:31	Additional Info Liner through mh B-...	

Normal Defects			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	2	4	2	2	4
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code	ID	Length									