



Defect Listing

Pipe Segment Refere... B-23_B-22	City Oliver Springs	Street pride rd	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH B-23	Total Length 126.3	Year Laid	Shape Circular	Location Details	
DS Manhole B-22	Length surveyed 55.3	Year Renewed	Height 8	Width 8	Pipe Joint... 4


SPR 7	MPR N/A	PO Number 4397-03	Customer GRW
SPRI 3.5	MPRI N/A	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR 4131	QMR N/A		
OPR 7	Surveyed By Charlie Gordon	Direction Upstream	Date 20150903
OPRI 3.5	Certificate Number U-615-07000491	Pre-Cleaning Jetting	Time 15:07
	Date Cleaned 20150910	End Time 15:14	Weather Dry
		Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: B-22									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
10.2 ft.	Fracture Longitudinal				0	<input type="checkbox"/>	6		3
20.4 ft.	Fracture Multiple				0	<input type="checkbox"/>	5	6	4
55.3 ft.	Survey Abandoned				0	<input type="checkbox"/>			
Remarks: COMPLETED LINE									



Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
B-23_B-22	Oliver Springs	pride rd	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
B-23	126.3		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
B-22	55.3		8	8	4




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: B-22



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 10.2 ft. Grade: 3
Condition: Fracture Longitudinal
Remarks: N/A




Distance: 20.4 ft. Grade: 4
Condition: Fracture Multiple
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
B-23_B-22	Oliver Springs	pride rd	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
B-23	126.3		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
B-22	55.3		8	8	4



Distance: 55.3 ft. Grade: 0
Condition: Survey Abandoned
Remarks: COMPLETED LINE



PACP Conditions

Pipe Segment Refere... B-23_B-22	City Oliver Springs	Street pride rd	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH B-23	Total Length 126.3	Year Laid	Shape Circular	Location Details	
DS Manhole B-22	Length surveyed 55.3	Year Renewed	Height 8	Width 8	Pipe Joint... 4
SPR 7	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI 3.5	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR 4131	QMR N/A	Direction Upstream		Date 20150903	
OPR 7	Surveyed By Charlie Gordon	Pre-Cleaning Jetting		Media label	
OPRI 3.5	Certificate Number U-615-07000491	Time 15:07		Weather Dry	
Date Cleaned 20150910			End Time 15:14		Additional Info

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	1	3	3	0	0	3	1	3
			4	1	4	4	0	0	4	1	4
			5	0	0	5	0	0	5	0	0
Code	ID	Length									
</											