ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Defect Listing

Pipe Segme	ent Refere	С	ity	Street	Mat	erial	Location C	Sewer Use		
B-24	_B-23	Oliver	Springs	Pride Rd	Concrete F	Pipe (non	Light High	Sanitary		
Upstre	am MH	Total I	_ength	Year Laid	Sh	ape	Location Deta			
B-	24	35	1.3		Circ	Circular				
DS Ma	anhole	Length s	surveyed	Year Renewed	Height Width		Height Width Pipe Jo		Width Pipe Joint 8 4	
B-	23	35	1.3		8	8				
SPR	N/A	MPR	2	PO Number			Customer			
0001	-	MDDI		4397-03 Work Order		GRW				
SPRI	N/A	MPRI	2			Purpose				
QSR	N/A	QMR	2100	4397-02		Pre-	-Rehabilitation Survey			
Ol	PR	Surve	yed By	Direction	Da	ate	Media	alabel		
2	2	Charlie_	Gordon	Downstream	2015	0903				
OF	PRI	Certificat	e Number	Pre-Cleaning	Tir	me	Weather			
:	2		7000491	Jetting	13	:13	Dry			
		Date C	leaned	Er		End Time		Additional Info		
		2015	0903		13:38					

Distance	Condition	Cont. Dfct.	Values			laint	Clock Position		0
	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	B-24			•					
0.0 ft.	Water Level				5				
10.9 ft.	Tap Factory Made Capped		6		0		9		
40.4 ft.	Tap Factory Made		6		0		3		
95.7 ft.	Tap Factory Made Capped		6		0		9		
112.2 ft.	Tap Factory Made		6		0		3		
126.8 ft.	Obstacle Other				5		6		2
Remarks:	TOOL			•					
181.1 ft.	Tap Factory Made		6		0		3		
223.8 ft.	Tap Factory Made		6		0		3		
308.4 ft.	Tap Factory Made		6		0		3		
350.4 ft.	Water Level				5				
351.3 ft.	Access Point Manhole				0				
Remarks:	B-23			•	•				•





Image Report 4/Page

Pipe Segment Refere	City	Street	Mat	erial	Location C	Sewer Use
B-24_B-23	Oliver Springs	Pride Rd	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
B-24	351.3		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
B-23	351.3		8	8	4	,



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: B-24



Distance: 0.0 ft. Grade: 0


Condition: Water Level

Remarks: N/A



Distance: 10.9 ft. **Grade**: 0 **Condition**: Tap Factory Made Capped

Remarks: N/A



Distance: 40.4 ft. Grade: 0

Condition: Tap Factory Made


Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

Pipe Segment Refere	City	Street	Mat	erial	Location C	Sewer Use
B-24_B-23	Oliver Springs	Pride Rd	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
B-24	351.3		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
B-23	351.3		8	8	4	_



Distance: 95.7 ft. Grade: Condition:

Tap Factory Made Capped

Remarks: N/A



Distance: 112.2 ft. Grade:

Condition: Tap Factory Made

Remarks: N/A



Distance: 126.8 ft. Grade:

Condition: Obstacle Other

Remarks: TOOL



Distance: 181.1 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A





Image Report 4/Page

Pipe Segment Refere	City	Street	Mat	erial	Location C	Sewer Use
B-24_B-23	Oliver Springs	Pride Rd	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
B-24	351.3		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
B-23	351.3		8	8	4	,



Distance: 223.8 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 308.4 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 350.4 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 351.3 ft. Grade: 0

Condition: Access Point Manhole

Remarks: B-23



PACP Conditions

Pipe Segme	ent Refere	С	ity	Street	Mat	erial	Location C	Sewer Use	
B-24	_B-23	Oliver	Springs	Pride Rd	Concrete F	Pipe (non	Light High	Sanitary	
Upstre	am MH	Total Length		Year Laid	Shape		Location	Details	
B-	24	35	1.3		Circular Height Width		Width Pipe Joint		
DS M	anhole	Length s	surveyed	Year Renewed					
B-	23	35	1.3		8	8	4		
SPR	N/A	MPR	2	PO Number			Customer		
0001	NI/A	MPDI		4397-03	4397-03				
SPRI	N/A	MPRI	2	Work Order		Purpose			
QSR	N/A	QMR	2100	4397-02		Pre-	Rehabilitation S	urvey	
Ol	PR	Surve	yed By	Direction	D	ate	Media	alabel	
:	2	Charlie_	_Gordon	Downstream	2015	0903			
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
:	2 U-615-07000491		Jetting		13:13				
		Date C	leaned		End Time		Additional Info		
		2015	0903	13:38					

			Stru	ctural Rat	ings	0	& M Ratin	gs	Con	nbined Ra	tings
Normal	Defects		Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
			1	0	0	1	0	0	1	0	0
			2	0	0	2	1	2	2	1	2
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code I	ID Len	gth									
			Subtotals	0		Subtotals	1		Subtotals	1	
SUMMARY		Pipe Rating Structural Index		0 0	Pipe Rating O&M Index		2 2.0	Overall Pipe Rating Overall Index		2 2.0	
			Str. Qu	ick Rating	0000	O&M Qui	ick Rating	2100	Ovrl. Quick Rating		2100