ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Defect Listing

Pipe Segment Refere		С	ty	Street	Mat	erial	Location C	Sewer Use		
B-5_	_B-4	Oliver	Springs	Old Harriman Hwy	Fibreglass	Reinforc	einforc Light High Sa			
Upstream MH		Total I	_ength	Year Laid	Shape		Location	Details		
В	-5	32	9.2		Circ	ular	ular			
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width				
B	-4	32	9.2		10	10	N/A			
SPR	N/A	MPR	18	PO Number	PO Number			Customer		
0001	-			4397-03	GRW					
SPRI	N/A	MPRI	2	Work Order		Purpose				
QSR	N/A	QMR	2900	4397-02		Pre-Rehabilitation Survey				
OF	PR	Surve	ed By	Direction	Da	ate	Media	label		
1	8	Charlie_	Gordon	Upstream	2015	0915				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather			
2		U-615-07000491		Jetting	14:48		Dry			
		Date C	leaned	End Time		Additional Info				
		2015	0915		15	:01				

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Po	Clock Position	
Distance	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	B-4								
0.0 ft.	Water Level				5				
10.0 ft.	Water Level				10				
144.7 ft.	Water Level Sag	S01			10				2
173.9 ft.	Water Level Sag	F01			10				2
267.1 ft.	Water Level Sag	S02			15				2
279.9 ft.	Water Level Sag	F02			15				2
326.0 ft.	Water Level				5				
329.2 ft.	Access Point Manhole				0				
Remarks:	B-5			•					•





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use	
B-5_B-4	Oliver Springs	Old Harriman Hwy	Fibreglass Reinforc		Light High	Sanitary	
Upstream MH	Total Length	Year Laid	Shape		Location	n Details	
B-5	329.2		Circular				
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint		
B-4	329.2		10	10	N/A		



Distance: 0.0 ft. Grade: (

Condition: Access Point Manhole

Remarks: B-4



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 10.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 144.7 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
B-5_B-4	Oliver Springs	Old Harriman Hwy	Fibreglass Reinforc		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
B-5	329.2		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
B-4	329.2		10	10	N/A	



Distance: 173.9 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 267.1 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 279.9 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 326.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
B-5_B-4	Oliver Springs	Old Harriman Hwy	Fibreglass Reinforc		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
B-5	329.2		Circular			
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
B-4	329.2		10	10	N/A	ر ا



Distance: 329.2 ft. Grade: 0

Condition: Access Point Manhole

Remarks: B-5



PACP Conditions

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
B-5_	_B-4	Oliver	Springs	Old Harriman Hwy	Fibreglass	Reinforc	Light High	Sanitary	
Upstrea	am MH	Total I	Length	Year Laid	Sh	Shape		n Details	
В	-5	32	9.2		Circular				
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint		
В	-4	32	9.2		10	10	N/A		
SPR	N/A	MPR	18	PO Number	Customer				
SPRI	N/A	MPRI	2	4397-03					
SFRI	IN/A	IVIFIXI		Work Order					
QSR	N/A	QMR	2900	4397-02		Pre-Rehabilitation Survey			
OF	PR	Surve	yed By	Direction	Date		Media label		
1	8	Charlie_	_Gordon	Upstream	2015	20150915			
OF	OPRI		e Number	Pre-Cleaning	Time		Weather		
2		U-615-07000491		Jetting	14:48		Dry		
		Date C	leaned	End Time		Additional Info			
		2015	0915	15:01					

			Stru	ctural Rat	ings	0	& M Ratin	gs	Con	nbined Ra	tings
Normal Defects		Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	
				_	_		_	_	4	_	_
			1	0	0	2	0	0	2	0	0
			2	0	0	3	0	0	3	0	0
			3 4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
			5	0	0) o	0	0) 3	0	0
Contin	uous C	Defects									
Code	ID	Length									
MWLS	F01	29.2	0	0	0	2	6	12	2	6	12
MWLS	F02	12.8	0	0	0	2	3	6	2	3	6
			Subtotals	0		Subtotals	9		Subtotals	9	
SUMMARY		Pi	pe Rating	0	Pi	Pipe Rating		Overall Pi	pe Rating	18	
50	J.111117		Struct	ural Index	0	0	&M Index	2.0	Ove	erall Index	2.0
			Str. Qu	ick Rating	0000	O&M Qui	ick Rating	2900	Ovrl. Quick Rating		2900