



Defect Listing

Pipe Segment Refere... B-6_B-5	City Oliver Springs	Street Old Harriman HWY	Material Fibreglass Reinforc...	Location C... Yard	Sewer Use Sanitary
Upstream MH B-6	Total Length 331.3	Year Laid	Shape Circular	Location Details	
DS Manhole B-5	Length surveyed 331.3	Year Renewed	Height 10	Width 10	Pipe Joint... N/A

SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Charlie_Gordon	Direction Downstream	Date 20150915	Media label	
OPRI N/A	Certificate Number U-615-07000491	Pre-Cleaning No Pre-Cleaning	Time 11:35	Weather Dry	
Date Cleaned			End Time 11:53	Additional Info CCTV only ds mh is ...	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: B-6									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
329.8 ft.	Water Level				5	<input type="checkbox"/>			
331.3 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: B-5									



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
B-6_B-5	Oliver Springs	Old Harriman HWY	Fibreglass Reinforc...	Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
B-6	331.3		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
B-5	331.3		10	10	N/A



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: B-6



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 329.8 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 331.3 ft. Grade: 0
Condition: Access Point Manhole
Remarks: B-5



Pipe Segment Refere... B-6_B-5	City Oliver Springs	Street Old Harriman HWY	Material Fibreglass Reinforc...		Location C... Yard	Sewer Use Sanitary
Upstream MH B-6	Total Length 331.3	Year Laid	Shape Circular		Location Details	
DS Manhole B-5	Length surveyed 331.3	Year Renewed	Height 10	Width 10	Pipe Joint... N/A	
SPR N/A	MPR N/A	PO Number 4397-03			Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02			Purpose	
QSR N/A	QMR N/A				Pre-Rehabilitation Survey	
OPR N/A	Surveyed By Charlie_Gordon	Direction Downstream	Date 20150915		Media label	
OPRI N/A	Certificate Number U-615-07000491	Pre-Cleaning No Pre-Cleaning	Time 11:35		Weather Dry	
Date Cleaned			End Time 11:53		Additional Info CCTV only ds mh is ...	

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
<div>Continuous Defects</div> <div>CodeIDLength</div> <div></div>			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
				</							