



Defect Listing

Pipe Segment Refere... B-8_B-7	City Oliver Springs	Street Old Harriman Hwy	Material Fibreglass Reinforc...	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH B-8	Total Length 315.1	Year Laid	Shape Circular	Location Details	
DS Manhole B-7	Length surveyed 315.1	Year Renewed	Height 10	Width 10	Pipe Joint... N/A


SPR N/A	MPR 8	PO Number 4397-03	Customer GRW
SPRI N/A	MPRI 2	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR N/A	QMR 2400		
OPR 8	Surveyed By Charlie Gordon	Direction Downstream	Date 20150915
OPRI 2	Certificate Number U-615-07000491	Pre-Cleaning Jetting	Time 10:09
	Date Cleaned 20150915	End Time 10:29	Weather Damp
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: B-8									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
178.8 ft.	Water Level Sag	S01			15	<input type="checkbox"/>			2
188.6 ft.	Water Level Sag	F01			15	<input type="checkbox"/>			2
206.0 ft.	Water Level Sag	S02			20	<input type="checkbox"/>			2
212.6 ft.	Water Level Sag	F02			20	<input type="checkbox"/>			2
311.3 ft.	Water Level Sag				25	<input type="checkbox"/>			2
313.6 ft.	Water Level				30	<input type="checkbox"/>			
315.1 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: B-7									




Image Report 4/Page

Pipe Segment Refere... B-8_B-7	City Oliver Springs	Street Old Harriman Hwy	Material Fibreglass Reinforc...		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH B-8	Total Length 315.1	Year Laid	Shape Circular		Location Details	
DS Manhole B-7	Length surveyed 315.1	Year Renewed	Height 10	Width 10	Pipe Joint...	N/A



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: B-8



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 178.8 ft. Grade: 2
Condition: Water Level Sag
Remarks: N/A




Distance: 188.6 ft. Grade: 2
Condition: Water Level Sag
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
B-8_B-7	Oliver Springs	Old Harriman Hwy	Fibreglass Reinforc...	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
B-8	315.1		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
B-7	315.1		10	10	N/A




Distance: 206.0 ft. Grade: 2
Condition: Water Level Sag
Remarks: N/A



Distance: 212.6 ft. Grade: 2
Condition: Water Level Sag
Remarks: N/A



Distance: 311.3 ft. Grade: 2
Condition: Water Level Sag
Remarks: N/A




Distance: 313.6 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
B-8_B-7	Oliver Springs	Old Harriman Hwy	Fibreglass Reinforc...	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
B-8	315.1		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
B-7	315.1		10	10	N/A



Distance: 315.1 ft. Grade: 0
Condition: Access Point Manhole
Remarks: B-7



Pipe Segment Refere... B-8_B-7	City Oliver Springs	Street Old Harriman Hwy	Material Fibreglass Reinforc...		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH B-8	Total Length 315.1	Year Laid	Shape Circular		Location Details	
DS Manhole B-7	Length surveyed 315.1	Year Renewed	Height 10	Width 10	Pipe Joint... N/A	
SPR N/A	MPR 8	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI 2	Work Order 4397-02		Purpose		
QSR N/A	QMR 2400			Pre-Rehabilitation Survey		
OPR 8	Surveyed By Charlie_Gordon	Direction Downstream	Date 20150915		Media label	
OPRI 2	Certificate Number U-615-07000491	Pre-Cleaning Jetting	Time 10:09		Weather Damp	
Date Cleaned 20150915			End Time 10:29		Additional Info	

[illegible]