



Defect Listing

Pipe Segment Refere... B1-1_B-11	City Oliver Springs	Street Cemetery Rd	Material Fibreglass Reinforc...	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH B1-1	Total Length	Year Laid	Shape Circular	Location Details	
DS Manhole B-11	Length surveyed 328.4	Year Renewed	Height 8	Width 8	Pipe Joint... N/A

SPR 3	MPR N/A	PO Number 4397-03	Customer GRW
SPRI 3	MPRI N/A	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR 3100	QMR N/A		
OPR 3	Surveyed By Charlie_Gordon	Direction Downstream	Date 20150911
OPRI 3	Certificate Number U-615-07000491	Pre-Cleaning Jetting	Time 12:25
	Date Cleaned 20150911	End Time 12:40	Weather Damp
			Media label
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: B1-1									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
326.9 ft.	Lining Failure Overcut Connection				0	<input type="checkbox"/>	8	1	3
328.4 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: B-11									



Image Report 4/Page


Pipe Segment Refere... B1-1_B-11	City Oliver Springs	Street Cemetery Rd	Material Fibreglass Reinforc...		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH B1-1	Total Length	Year Laid	Shape Circular		Location Details	
DS Manhole B-11	Length surveyed 328.4	Year Renewed	Height 8	Width 8	Pipe Joint...	N/A




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: B1-1



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 326.9 ft. Grade: 3
Condition: Lining Failure Overcut Connection
Remarks: N/A



Distance: 328.4 ft. Grade: 0
Condition: Access Point Manhole
Remarks: B-11



PACP Conditions

Pipe Segment Refere... B1-1_B-11	City Oliver Springs	Street Cemetery Rd	Material Fibreglass Reinforc...	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH B1-1	Total Length	Year Laid	Shape Circular	Location Details	
DS Manhole B-11	Length surveyed 328.4	Year Renewed	Height 8	Width 8	Pipe Joint... N/A
SPR 3	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI 3	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR 3100	QMR N/A	Direction Downstream		Date 20150911	Media label
OPR 3	Surveyed By Charlie Gordon	Pre-Cleaning Jetting		Time 12:25	Weather Damp
OPRI 3	Certificate Number U-615-07000491	Date Cleaned 20150911		End Time 12:40	Additional Info

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	1	3	3	0	0	3	1	3
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code	ID	Length									