



## Defect Listing

Pipe Segment Refere... <b>B3-3_B3-2</b>	City <b>Oliver Springs</b>	Street <b>Kentucky St</b>	Material <b>Concrete Pipe (non-...</b>	Location C... <b>Light High...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>B3-3</b>	Total Length <b>167.7</b>	Year Laid	Shape <b>Circular</b>	Location Details	
DS Manhole <b>B3-2</b>	Length surveyed <b>167.7</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>4</b>

SPR <b>3</b>	MPR <b>N/A</b>	PO Number <b>4397-03</b>	Customer <b>GRW</b>
SPRI <b>3</b>	MPRI <b>N/A</b>	Work Order <b>4397-02</b>	Purpose <b>Pre-Rehabilitation Survey</b>
QSR <b>3100</b>	QMR <b>N/A</b>		
OPR <b>3</b>	Surveyed By <b>Charlie Gordon</b>	Direction <b>Downstream</b>	Date <b>20150908</b>
OPRI <b>3</b>	Certificate Number <b>U-615-07000491</b>	Pre-Cleaning <b>Jetting</b>	Time <b>13:47</b>
	Date Cleaned <b>20150908</b>	End Time <b>13:54</b>	Weather <b>Dry</b>
			Media label
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: B3-3									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
6.0 ft.	Tap Factory Made Capped		6		0	<input type="checkbox"/>	9		
95.8 ft.	Hole				0	<input type="checkbox"/>	10		3
97.4 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
164.8 ft.	Water Level				5	<input type="checkbox"/>			
167.7 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: B3-2									




## Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
<b>B3-3_B3-2</b>	<b>Oliver Springs</b>	<b>Kentucky St</b>	<b>Concrete Pipe (non-...</b>	<b>Light High...</b>	<b>Sanitary</b>
<b>Upstream MH</b>	Total Length	Year Laid	<b>Shape</b>	Location Details	
<b>B3-3</b>	<b>167.7</b>		<b>Circular</b>		
<b>DS Manhole</b>	<b>Length surveyed</b>	Year Renewed	<b>Height</b>	Width	Pipe Joint...
<b>B3-2</b>	<b>167.7</b>		<b>8</b>	<b>8</b>	<b>4</b>




Distance: 0.0 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: B3-3



Distance: 0.0 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 6.0 ft. Grade: 0  
Condition: Tap Factory Made Capped  
Remarks: N/A




Distance: 95.8 ft. Grade: 3  
Condition: Hole  
Remarks: N/A




## Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
<b>B3-3_B3-2</b>	<b>Oliver Springs</b>	<b>Kentucky St</b>	<b>Concrete Pipe (non-...</b>	<b>Light High...</b>	<b>Sanitary</b>
<b>Upstream MH</b>	Total Length	Year Laid	<b>Shape</b>	Location Details	
<b>B3-3</b>	<b>167.7</b>		<b>Circular</b>		
<b>DS Manhole</b>	<b>Length surveyed</b>	Year Renewed	<b>Height</b>	Width	Pipe Joint...
<b>B3-2</b>	<b>167.7</b>		<b>8</b>	<b>8</b>	<b>4</b>



Distance: 97.4 ft. Grade: 0  
Condition: Tap Factory Made  
Remarks: N/A



Distance: 164.8 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 167.7 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: B3-2



## PACP Conditions

Pipe Segment Refere... <b>B3-3_B3-2</b>	City <b>Oliver Springs</b>	Street <b>Kentucky St</b>	Material <b>Concrete Pipe (non-...</b>	Location C... <b>Light High...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>B3-3</b>	Total Length <b>167.7</b>	Year Laid	Shape <b>Circular</b>	Location Details	
DS Manhole <b>B3-2</b>	Length surveyed <b>167.7</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>4</b>
SPR <b>3</b>	MPR <b>N/A</b>	PO Number <b>4397-03</b>		Customer <b>GRW</b>	
SPRI <b>3</b>	MPRI <b>N/A</b>	Work Order <b>4397-02</b>		Purpose <b>Pre-Rehabilitation Survey</b>	
QSR <b>3100</b>	QMR <b>N/A</b>	Direction <b>Downstream</b>		Date <b>20150908</b>	
OPR <b>3</b>	Surveyed By <b>Charlie Gordon</b>	Pre-Cleaning <b>Jetting</b>		Media label	
OPRI <b>3</b>	Certificate Number <b>U-615-07000491</b>	Time <b>13:47</b>		Weather <b>Dry</b>	
Date Cleaned <b>20150908</b>			End Time <b>13:54</b>		Additional Info

Normal Defects			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	1	3	3	0	0	3	1	3
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code	ID	Length									