ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Defect Listing

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
B4-4_B4-3 Upstream MH		Oliver Springs		Kansas ST	Concrete F	Concrete Pipe (non		Sanitary	
		Total	_ength	Year Laid	Sha	ape	Location	n Details	
B4	1-4	21	3.2		Circ	ular			
DS Ma	anhole	Length :	surveyed	Year Renewed	Height	Width	Width Pipe Joint		
B4	1-3	21	3.2		8	8 8 4			
SPR	3	MPR	16	PO Number 4397-03		Customer GRW			
-									
SPRI	3	MPRI	2	Work Order					
QSR	3100	QMR	2800	4397-02		Pre-Rehabilitation Survey			
OF	PR	Surveyed By		Direction	Da	Date		a label	
1	9	Charlie_Gordon		Downstream	2015	20150904			
OF	PRI	Certificate Number		Pre-Cleaning	Tir	Time			
2.1		U-615-07000491		Jetting 13		13:05			
		Date C	leaned	End	End Time		Additional Info		
		2015	0904	13:18					

Distance	Condition	Court Diet	Values			,	Clock Position		0
Distance	Condition	Cont. Dfct.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	B4-4			•	•				
0.0 ft.	Water Level				5				
6.0 ft.	Tap Factory Made Active		6		0		3		
29.2 ft.	Water Level Sag	S01			10				2
48.2 ft.	Water Level Sag	F01			10				2
57.5 ft.	Water Level Sag	S02			10				2
74.0 ft.	Water Level Sag	F02			10				2
92.2 ft.	Water Level Sag	S03			10				2
99.1 ft.	Water Level Sag	F03			10				2
164.7 ft.	Hole				0	4	10		3
167.0 ft.	Tap Factory Made		6		0		12		
210.6 ft.	Water Level				5				
213.2 ft.	Access Point Manhole				0				
Remarks:	B4-3								





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
B4-4_B4-3	Oliver Springs	Kansas ST	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
B4-4	213.2		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
B4-3	213.2		8	8	4	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole


Remarks: B4-4



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance:6.0 ft.Grade:Condition:Tap Factory Made Active

Remarks: N/A



Distance: 29.2 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
B4-4_B4-3	Oliver Springs	Kansas ST	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
B4-4	213.2		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
B4-3	213.2		8	8	4	,



Distance: 48.2 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 57.5 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 74.0 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 92.2 ft. Grade: 2

Condition: Water Level Sag


Remarks: N/A





Image Report 4/Page


Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
B4-4_B4-3	Oliver Springs	Kansas ST	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
B4-4	213.2		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
B4-3	213.2		8	8	4	



Distance: 99.1 ft. Grade: 2


Condition: Water Level Sag

Remarks: N/A



Distance: 164.7 ft. Grade: 3

Condition: Hole Remarks: N/A



Distance: 167.0 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 210.6 ft. Grade: 0

Condition: Water Level

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
B4-4_B4-3	Oliver Springs	Kansas ST	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
B4-4	213.2		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
B4-3	213.2		8	8	4	,



Distance: 213.2 ft. Grade: 0

Condition: Access Point Manhole

Remarks: B4-3



PACP Conditions

Pipe Segment Refere		City		Street	Material		Location C	Sewer Use	
B4-4_B4-3		Oliver Springs		Kansas ST	Concrete F	Concrete Pipe (non		Sanitary	
Upstre	Upstream MH Total Length		Length	Year Laid	Shape		Location	Details	
B	4-4	21	3.2		Circ	ular			
DS M	anhole	Length s	surveyed	Year Renewed	Height	Width	Vidth Pipe Joint		
B	B4-3		3.2		8	8	4		
SPR	3	MPR	16	PO Number			Customer		
0001	•	MDDI		4397-03		GRW			
SPRI	3	MPRI	2	Work Order	Pre-l		Purpose e-Rehabilitation Survey		
QSR	3100	QMR	2800	4397-02					
Ol	PR	Surveyed By		Direction	Date		Media label		
1	9	Charlie_	_Gordon	Downstream	20150904				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
2	2.1		7000491	Jetting	13:05		Dry		
		Date C	leaned	End Time		Additional Info			
		2015	0904	13:18					

			Structural Ratings			0	& M Ratin	gs	Com	nbined Ra	tings
Normal Defects		Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	
				_	_		_	_	4	_	_
			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	1	3	3	0	0	3	1	3
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continu	uous C	Defects									
Code	ID	Length									
MWLS	F01	19.0	0	0	0	2	4	8	2	4	8
MWLS	F02	16.5	0	0	0	2	3	6	2	3	6
MWLS	F03	6.9	0	0	0	2	1	2	2	1	2
			Subtotals	1		Subtotals	8		Subtotals	9	
			Captotals	ı		Cabiolais	U		Captotals	3	
SUMMARY		Pi	pe Rating	3	Pi	pe Rating	16	Overall Pi	ipe Rating	19	
.	- ······		Struct	ural Index	3.0	0	&M Index	2.0	Overall Index		2.1
			Str. Qu	ick Rating	3100	O&M Qui	ick Rating	2800	Ovrl. Quick Rating		3128