



## Defect Listing

Pipe Segment Refere... <b>B5-1_B-21</b>	City <b>Oliver Springs</b>	Street <b>Highway#61</b>	Material <b>Fibreglass Reinforc...</b>	Location C... <b>Main Highw...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>B5-1</b>	Total Length <b>41.9</b>	Year Laid	Shape <b>Circular</b>	Location Details	
DS Manhole <b>B-21</b>	Length surveyed <b>41.9</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>N/A</b>

SPR <b>N/A</b>	MPR <b>N/A</b>	PO Number <b>4397-03</b>		Customer <b>GRW</b>	
SPRI <b>N/A</b>	MPRI <b>N/A</b>	Work Order <b>4397-02</b>		Purpose <b>Pre-Rehabilitation Survey</b>	
QSR <b>N/A</b>	QMR <b>N/A</b>				
OPR <b>N/A</b>	Surveyed By <b>Charlie_Gordon</b>	Direction <b>Upstream</b>	Date <b>20150904</b>	Media label	
OPRI <b>N/A</b>	Certificate Number <b>U-615-07000491</b>	Pre-Cleaning <b>Jetting</b>	Time <b>09:08</b>	Weather <b>Dry</b>	
Date Cleaned <b>20150904</b>			End Time <b>09:13</b>	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: B-21									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
41.9 ft.	Survey Abandoned				0	<input type="checkbox"/>			
Remarks: COMPLETE LINE									



## Image Report 4/Page


Pipe Segment Refere... <b>B5-1_B-21</b>	City <b>Oliver Springs</b>	Street <b>Highway#61</b>	Material <b>Fibreglass Reinforc...</b>		Location C... <b>Main Highw...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>B5-1</b>	Total Length <b>41.9</b>	Year Laid	Shape <b>Circular</b>		Location Details	
DS Manhole <b>B-21</b>	Length surveyed <b>41.9</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint...	
					<b>N/A</b>	



Distance: 0.0 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: B-21



Distance: 0.0 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 41.9 ft. Grade: 0  
Condition: Survey Abandoned  
Remarks: COMPLETE LINE



Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
B5-1_B-21	Oliver Springs	Highway#61	Fibreglass Reinforc...	Main Highw...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
B5-1	41.9		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
B-21	41.9		8	8	N/A
SPR	N/A	MPR	N/A	PO Number	
SPRI	N/A	MPRI	N/A	Customer	
QSR	N/A	QMR	N/A	GRW	
				Work Order	
				Purpose	
				Pre-Rehabilitation Survey	
OPR	Surveyed By	Direction	Date	Media label	
N/A	Charlie_Gordon	Upstream	20150904		
OPRI	Certificate Number	Pre-Cleaning	Time	Weather	
N/A	U-615-07000491	Jetting	09:08	Dry	
	Date Cleaned		End Time	Additional Info	
	20150904		09:13		

[illegible]