505-341-0109



Defect Listing

Pipe Segme	ent Refere	С	ity	Street	Mat	erial	Location C	Sewer Use	
C-14_	C-13	Oliver	Springs	Maple ST	Fibreglass	Reinforc	Yard Sanita		
Upstrea	am MH	Total Length		Year Laid	Shape		Location	n Details	
C-	14	35	4.2		Circ	ular			
DS Ma	nhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint		
C-	13	35	4.2		8	8	N/A		
SPR	N/A	MPR	10	PO Number			Customer		
ODDI	NI/A	MDDI		4397-03		GRW			
SPRI	N/A	MPRI	2	Work Order		Purpose			
QSR	N/A	QMR	2500	4397-02		Pre-	Rehabilitation S	urvey	
OF	PR	Surve	yed By	Direction	Da	ate	Media	a label	
1	0	Barry_	Rogers	Downstream	2015	0812			
OP	rRI	Certificate	e Number	Pre-Cleaning	Ti	Time Weather			
2	2	U-1012	2-16405	No Pre-Cleaning	15:49		Dry		
		Date C	leaned	End Time		Additional Info			
					15	:58			

Distance	Condition	Cant Diat	Values			Joint	Clock Position		0
Distance	Condition	Cont. Dfct.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	C-14			•					
0.0 ft.	Water Level				10				
21.8 ft.	Water Level Sag				20				2
29.0 ft.	Tap Factory Made Defective		6		0		3		2
64.3 ft.	Water Mark				20				
128.7 ft.	Water Level Sag				20				2
202.5 ft.	Water Level Sag				10				2
289.3 ft.	Water Level Sag				10				2
351.4 ft.	Water Level				10				
354.2 ft.	Access Point Manhole				0				
Remarks:	C-13								•





Image Report 4/Page


Pipe Segment Refere	City	Street	Mat	erial	Location C	Sewer Use
C-14_C-13	Oliver Springs	Maple ST	Fibreglass	Fibreglass Reinforc		Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
C-14	354.2		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
C-13	354.2		8	8	N/A	,



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: C-14



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 21.8 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 29.0 ft. **Grade**: 2 **Condition**: Tap Factory Made Defective

Remarks: N/A





Image Report 4/Page

Pipe Segment Refere	City	Street	Mat	erial	Location C	Sewer Use
C-14_C-13	Oliver Springs	Maple ST	Fibreglass	Reinforc	Yard	Sanitary
Upstream MH	Total Length	Year Laid	Sh	ape	Location	Details
C-14	354.2		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
C-13	354.2		8	8	N/A	



Distance: 64.3 ft. Grade: 0

Condition: Water Mark Remarks: N/A



Distance: 128.7 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 202.5 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 289.3 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Image Report 4/Page

Pipe Segment Refere	City	Street	Mat	erial	Location C	Sewer Use
C-14_C-13	Oliver Springs	Maple ST	Fibreglass	Reinforc	Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
C-14	354.2		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
C-13	354.2		8	8	N/A	



Distance: 351.4 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 354.2 ft. Grade: (

Condition: Access Point Manhole

Remarks: C-13



PACP Conditions

Pipe Segme	ent Refere	C	ity	Street	Ma	terial	Location C	Sewer Use	
C-14	_C-13	Oliver	Springs	Maple ST	Fibreglass	Reinforc	Yard	Sanitary	
Upstre	am MH	Total Length		Year Laid	Sh	Shape		n Details	
C-	-14	35	4.2		Circ	Circular Height Width			
DS Ma	anhole	Length s	surveyed	Year Renewed	Height				
C-	·13	35	4.2		8	8	N/A		
SPR	N/A	MPR	10	PO Number			Customer		
SPRI	N/A	MPRI	2	4397-03			GRW Purpose		
SPRI	IN/A	IVIPRI		Work Order	Work Order				
QSR	N/A	QMR	2500	4397-02		Pre-	-Rehabilitation Survey		
Ol	PR	Surve	yed By	Direction	D	ate	Media	a label	
1	0	Barry_	Rogers	Downstream	20150812				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
2	2		2-16405	No Pre-Cleaning	15	5:49	Dry		
		Date C	Cleaned	End	Time	Additional Info			
					15	5:58			

			Stru	ctural Rat	ings	О	& M Ratin	gs	Con	nbined Ra	tings
Normal	Defe	cts	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
			1	0	0	1	0	0	1	0	0
			2	0	0	2	0 5	0 10	2	0	0
			3	0	0	3	0	0	3	5 0	10 0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
			-		ŭ		Ŭ				ŭ
Continuo	us De	fects									
Code I	ID L	_ength									
			Subtotals	0		Subtotals	5		Subtotals	5	
SUMMARY		γ	Pi	pe Rating	0	Pi	pe Rating	10	Overall Pipe Rating		10
		-	Struct	ural Index	0	0	&M Index	2.0	Ove	erall Index	2.0
			Str. Qu	ick Rating	0000	O&M Qui	ick Rating	2500	Ovrl. Qu	ick Rating	2500