



Defect Listing

Pipe Segment Refere... C-15_C-14	City Oliver Springs	Street Easement	Material Fibreglass Reinforc...	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH C-15	Total Length 172.1	Year Laid	Shape Circular	Location Details	
DS Manhole C-14	Length surveyed 172.1	Year Renewed	Height 8	Width 8	Pipe Joint... N/A

SPR N/A	MPR 8	PO Number 4397-03	Customer GRW
SPRI N/A	MPRI 4	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR N/A	QMR 4200		
OPR 8	Surveyed By Barry Rogers	Direction Downstream	Date 20150724
OPRI 4	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 13:22
	Date Cleaned 20150724	End Time 13:29	Weather Saturated
			Media label
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C-15									
0.0 ft.	Water Level				30	<input type="checkbox"/>			
65.7 ft.	Camera Underwater	S01			0	<input type="checkbox"/>			4
74.5 ft.	Camera Underwater	F01			0	<input type="checkbox"/>			4
79.4 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
170.1 ft.	Water Level				30	<input type="checkbox"/>			
172.1 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C-14									




Image Report 4/Page


Pipe Segment Refere... C-15_C-14	City Oliver Springs	Street Easement	Material Fibreglass Reinforc...		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH C-15	Total Length 172.1	Year Laid	Shape Circular		Location Details	
DS Manhole C-14	Length surveyed 172.1	Year Renewed	Height 8	Width 8	Pipe Joint...	N/A




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C-15



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 65.7 ft. Grade: 4
Condition: Camera Underwater
Remarks: N/A




Distance: 74.5 ft. Grade: 4
Condition: Camera Underwater
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C-15_C-14	Oliver Springs	Easement	Fibreglass Reinforc...	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
C-15	172.1		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
C-14	172.1		8	8	N/A



Distance: 79.4 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 170.1 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 172.1 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C-14



PACP Conditions

Pipe Segment Refere... C-15_C-14	City Oliver Springs	Street Easement	Material Fibreglass Reinforc...	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH C-15	Total Length 172.1	Year Laid	Shape Circular	Location Details	
DS Manhole C-14	Length surveyed 172.1	Year Renewed	Height 8	Width 8	Pipe Joint... N/A
SPR N/A	MPR 8	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI 4	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR 4200				
OPR 8	Surveyed By Barry Rogers	Direction Downstream	Date 20150724	Media label	
OPRI 4	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 13:22	Weather Saturated	
Date Cleaned 20150724			End Time 13:29	Additional Info	

Normal Defects			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code	ID	Length	0	0	0	4	2	8	4	2	8
MCU	F01	8.8									
			Subtotals	0		Subtotals	2		Subtotals	2	
SUMMARY			Pipe Rating		0	Pipe Rating		8	Overall Pipe Rating		8
			Structural Index		0	O&M Index		4.0	Overall Index		4.0
			Str. Quick Rating		0000	O&M Quick Rating		4200	Ovrl. Quick Rating		4200