



Defect Listing

Pipe Segment Refere... C-16_C-15	City Oliver Springs	Street Steward Ln	Material Fibreglass Reinforc...	Location C... Light High...	Sewer Use Sanitary
Upstream MH C-16	Total Length 236.7	Year Laid	Shape Circular	Location Details	
DS Manhole C-15	Length surveyed 236.7	Year Renewed	Height 8	Width 8	Pipe Joint... N/A

SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150720	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 08:14	Weather Dry	
Date Cleaned 20150720			End Time 08:34	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C-16									
0.0 ft.	Water Level				10	<input type="checkbox"/>			
21.8 ft.	Tap Factory Made Active		6		0	<input type="checkbox"/>	3		
37.7 ft.	Tap Factory Made Active		4		0	<input type="checkbox"/>	12		
80.7 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
234.7 ft.	Water Level				10	<input type="checkbox"/>			
236.7 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C-15									




Image Report 4/Page


Pipe Segment Refere... C-16_C-15	City Oliver Springs	Street Steward Ln	Material Fibreglass Reinforc...		Location C... Light High...	Sewer Use Sanitary
Upstream MH C-16	Total Length 236.7	Year Laid	Shape Circular		Location Details	
DS Manhole C-15	Length surveyed 236.7	Year Renewed	Height 8	Width 8	Pipe Joint...	
					N/A	




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C-16



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 21.8 ft. Grade: 0
Condition: Tap Factory Made Active
Remarks: N/A




Distance: 37.7 ft. Grade: 0
Condition: Tap Factory Made Active
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere... C-16_C-15	City Oliver Springs	Street Steward Ln	Material Fibreglass Reinforc...		Location C... Light High...	Sewer Use Sanitary
Upstream MH C-16	Total Length 236.7	Year Laid	Shape Circular		Location Details	
DS Manhole C-15	Length surveyed 236.7	Year Renewed	Height 8	Width 8	Pipe Joint...	
					N/A	



Distance: 80.7 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 234.7 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 236.7 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C-15



PACP Conditions

Pipe Segment Refere... C-16_C-15	City Oliver Springs	Street Steward Ln	Material Fibreglass Reinforc...	Location C... Light High...	Sewer Use Sanitary
Upstream MH C-16	Total Length 236.7	Year Laid	Shape Circular	Location Details	
DS Manhole C-15	Length surveyed 236.7	Year Renewed	Height 8	Width 8	Pipe Joint... N/A
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A	Direction Downstream		Date 20150720	
OPR N/A	Surveyed By Barry Rogers	Pre-Cleaning Jetting		Media label	
OPRI N/A	Certificate Number U-1012-16405	Time 08:14		Weather Dry	
Date Cleaned 20150720			End Time 08:34		Additional Info

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code	ID	Length									
							</				