



Defect Listing

Pipe Segment Refere... C-24_C-23	City Oliver Springs	Street edmonds dr	Material Fibreglass Reinf...	Location C... Yard	Sewer Use Sanitary
Upstream MH C-24	Total Length 327.8	Year Laid	Shape Circular	Location Details	
DS Manhole C-23	Length surveyed 327.8	Year Renewed	Height 8	Width 8	Pipe Joint... N/A


SPR N/A	MPR N/A	PO Number 4397-03	Customer GRW
SPRI N/A	MPRI N/A	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR N/A	QMR N/A		
OPR N/A	Surveyed By Barry Rogers	Direction Upstream	Date 20150716
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 12:46
	Date Cleaned 20150716	End Time 13:09	Weather Dry
		Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C-23									
0.0 ft.	Water Level				20	<input type="checkbox"/>			
207.4 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
326.2 ft.	Water Level				10	<input type="checkbox"/>			
327.8 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C-24									



Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C-24_C-23	Oliver Springs	edmonds dr	Fibreglass Reinforc...	Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
C-24	327.8		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
C-23	327.8		8	8	N/A



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C-23



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 207.4 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Distance: 326.2 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C-24_C-23	Oliver Springs	edmonds dr	Fibreglass Reinforc...	Yard	Sanitary
Upstream MH C-24	Total Length 327.8	Year Laid	Shape Circular	Location Details	
DS Manhole C-23	Length surveyed 327.8	Year Renewed	Height 8	Width 8	Pipe Joint... N/A



Distance: 327.8 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C-24



PACP Conditions

Pipe Segment Refere... C-24_C-23	City Oliver Springs	Street edmonds dr	Material Fibreglass Reinforc...	Location C... Yard	Sewer Use Sanitary
Upstream MH C-24	Total Length 327.8	Year Laid	Shape Circular	Location Details	
DS Manhole C-23	Length surveyed 327.8	Year Renewed	Height 8	Width 8	Pipe Joint... N/A
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A	Direction Upstream		Date 20150716	
OPR N/A	Surveyed By Barry Rogers	Pre-Cleaning Jetting		Time 12:46	
OPRI N/A	Certificate Number U-1012-16405	Date Cleaned 20150716		End Time 13:09	
			Media label		Weather Dry
			Additional Info		

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code	ID	Length									