

## **Defect Listing**

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
C-28_	_C-26	Oliver	Springs	Foxwood Cir	Concrete F	Pipe (non Easement/F		Sanitary	
Upstream MH		Total Length		Year Laid	Sha	ape	Location	Details	
C-	28	31	9.8		Circ	Circular			
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width Pipe Joint			
C-	26	31	9.8		8 8 4				
SPR	N/A	MPR	2	PO Number			Customer		
0001		MPDI		4397-03			GRW		
SPRI	N/A	MPRI	2	Work Order		Purpose			
QSR	N/A	QMR	2100	4397-02		Pre-Rehabilitation St		urvey	
OF	PR	Surve	yed By	Direction	Date Media label		label		
2	2	Barry_Rogers		Upstream	20150713				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
2	2 U-1012-16405		2-16405	Jetting 07:		07:54			
		Date C	leaned		End Time		Additional Info		
		2015	0713	08:12					

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Oneda
Distance	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	C-26								
0.0 ft.	Water Level				5				
2.9 ft.	Deposits Attached Grease				10		8		2
317.2 ft.	Water Level				5				
319.8 ft.	Access Point Manhole				0				
Remarks:	C-27								





## **Image Report 4/Page**

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
C-28_C-26	Oliver Springs	Foxwood Cir	Concrete Pipe (non		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
C-28	319.8		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
C-26	319.8		8	8	4	,



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: C-26



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



**Distance**: 2.9 ft. **Grade**: 2 **Condition**: Deposits Attached Grease

Remarks: N/A



Distance: 317.2 ft. Grade: 0

Condition: Water Level

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



## Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
C-28_C-26	Oliver Springs	Foxwood Cir	Concrete Pipe (non		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
C-28	319.8		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
C-26	319.8		8	8	4	ر ا



Distance: 319.8 ft. Grade: 0

Condition: Access Point Manhole

Remarks: C-27



## **PACP Conditions**

Pipe Segment Refere		С	ity	Street	Mat	erial	Location C	Sewer Use	
C-28_	_C-26	Oliver	Springs	Foxwood Cir	Concrete F	Pipe (non	Easement/R	Sanitary	
Upstre	am MH	Total Length Year Laid		Shape		Location Details			
C-	28	31	9.8		Circular				
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint		
C-	26	31	9.8		8	8 4			
SPR	N/A	MPR	2	PO Number			Customer		
2001	N1/A			4397-03			GRW		
SPRI	N/A	MPRI	2	Work Order		Purpose			
QSR	N/A	QMR	2100	4397-02		Pre-	e-Rehabilitation Survey		
OF	PR	Surve	yed By	Direction	Date		Media label		
2	2	Barry_	Rogers	Upstream 201507		0713			
OF	OPRI		e Number	Pre-Cleaning	Time		Weather		
2	2 U-1012-16405		Jetting	07:54		Damp			
		Date C	leaned		End Time		Additional Info		
		2015	0713		08:12				

			Stru	ctural Rat	ings	0	& M Ratin	gs	Con	nbined Ra	tings
Normal Defects		Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	
			1	0	0	1	0	0	1	0	0
			2	0	0	2	1	2	2	1	2
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code I	ID Len	gth									
			Subtotals	0		Subtotals	1		Subtotals	1	
SUMMARY		Struct	ipe Rating ural Index	0 0	0	pe Rating &M Index	2 2.0	Ove	ipe Rating erall Index	2 2.0	
			Str. Qu	ick Rating	0000	O&M Qui	ick Rating	2100	Ovrl. Qu	ick Rating	2100