ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Defect Listing

Pipe Segment Refere		City		Street	Material		Location C	Sewer Use	
C-31_C-30		Oliver Springs		Richaeds Dr	Concrete F	Pipe (non	Light High	Sanitary	
Upstream MH		Total I	_ength	Year Laid	Sh	ape	Location	n Details	
C-	31	20	9.1		Circ	cular			
DS Manhole		Length surveyed		Year Renewed	Height	Width	Pipe Joint		
C-30		20	9.1		8	8	4		
SPR	7	MPR	4	PO Number 4397-03 Work Order		Customer			
2001	4.0					GRW			
SPRI	1.8	MPRI	2			Purpose			
QSR	2311	QMR	2200	4397-02		Pre-Rehabilitation Survey			
OF	PR	Surve	/ed By	Direction	Date		te Media label		
1	1	Barry_Rogers		Downstream	20150710				
OP	RI	Certificate Number		Pre-Cleaning	Time		Weather		
1.8		U-1012-16405		Jetting	09:47		Dry		
	Date Cleaned					End Time		Additional Info	
		2015	0710	09:48					

D'-1	Condition	O Df	Values			1	Clock Position		Cundo
Distance	Condition	Cont. Dfct.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	C-31								
0.0 ft.	Water Level				5				
74.8 ft.	Tap Factory Made		6		0		9		
76.0 ft.	Joint Offset Medium				0				1
76.0 ft.	Repair Point Pipe Replaced				0				
Remarks:	cp to pvc								•
79.1 ft.	Material Change				0				
Remarks:	pvc to cp								
197.5 ft.	Joint Offset Large				0				2
198.5 ft.	Repair Point Pipe Replaced				0				
Remarks:	cp to pvc								
201.8 ft.	Tap Factory Made		6		0		3		
201.9 ft.	Water Level Sag				10				2
204.2 ft.	Joint Offset Large				0				2
208.1 ft.	Water Level Sag				20				2
209.1 ft.	Joint Offset Large				0				2
209.1 ft.	Survey Abandoned				0				
Remarks:	Unable to pass Off Set Joint			•					•





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
C-31_C-30	Oliver Springs	Richaeds Dr	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
C-31	209.1		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
C-30	209.1		8	8	4	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: C-31



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 74.8 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 76.0 ft. Grade: 1

Condition: Joint Offset Medium

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
C-31_C-30	Oliver Springs	Richaeds Dr	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Sh	Shape		n Details
C-31	209.1		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
C-30	209.1		8	8	4	



Distance: 76.0 ft. **Grade**: 0 **Condition**: Repair Point Pipe Replaced

Remarks: cp to pvc



Distance: 79.1 ft. Grade: 0

Condition: Material Change

Remarks: pvc to cp



Distance: 197.5 ft. Grade: 2

Condition: Joint Offset Large

Remarks: N/A



Distance: 198.5 ft. **Grade**: 0 **Condition**: Repair Point Pipe Replaced

Remarks: cp to pvc





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
C-31_C-30	Oliver Springs	Richaeds Dr	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location I	
C-31	209.1		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
C-30	209.1		8	8	4	ر ا



Distance: 201.8 ft. Grade: 0

Condition: Tap Factory Made


Remarks: N/A



Distance: 201.9 ft. Grade: 2

Condition: Water Level Sag


Remarks: N/A



Distance: 204.2 ft. Grade: 2

Condition: Joint Offset Large

Remarks: N/A



Distance: 208.1 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Image Report 4/Page


Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
C-31_C-30	Oliver Springs	Richaeds Dr	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
C-31	209.1		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
C-30	209.1		8	8	4	



Distance: 209.1 ft. Grade: 2

Condition: Joint Offset Large

Remarks: N/A



Distance: 209.1 ft. Grade: 0

Condition: Survey Abandoned

Remarks: Unable to pass Off Set Joint



PACP Conditions

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
C-31_C-30		Oliver Springs		Richaeds Dr	Concrete F	Concrete Pipe (non		Sanitary	
Upstrea	am MH	Total	Length	Year Laid	Sh	Shape		n Details	
C-31		20	9.1		Circ	cular			
DS Ma	anhole	Length:	surveyed	Year Renewed	Height	Width	Pipe Joint		
C-	C-30		9.1		8	8	4		
SPR	7	MPR 4		PO Number			Customer		
	·			4397-03			GRW		
SPRI	1.8	MPRI	2	Work Order					
QSR	2311	QMR	2200	4397-02		Pre-Rehabilitation Su			
OF	PR .	Surve	yed By	Direction	Date		Media label		
1	1	Barry_	Rogers	Downstream	20150710				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
1.8		U-1012	2-16405	Jetting	09:47		Dry		
	Date Cleaned					End Time		Additional Info	
		2015	0710	09:48					

	Stru	Structural Ratings			& M Ratin	gs	Con	nbined Ra	tings
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
	1	1	1	1	0	0	1	1	1
	2	3	6	2	2	4	2	5	10
	3	0	0	3	0	0	3	0	0
	4	0	0	4	0	0	4	0	0
	5	0	0	5	0	0	5	0	0
Continuous Defects Code ID Length	-								
	Subtotals	4		Subtotals	2		Subtotals	6	
SUMMARY	Struct	ipe Rating ural Index ick Rating	1.8	Pipe Rating 4 O&M Index 2.0 O&M Quick Rating 2200		Ove	ipe Rating erall Index ick Rating	11 1.8 2511	