



Defect Listing

Pipe Segment Refere... C1-1_C-1	City Oliver Springs	Street Strutt St	Material Fibreglass Reinf...	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH C1-1	Total Length 115.8	Year Laid	Shape Circular	Location Details	
DS Manhole C-1	Length surveyed 115.8	Year Renewed	Height 8	Width 8	Pipe Joint... N/A


SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150727	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 07:31	Weather Dry	
Date Cleaned 20150727			End Time 07:39	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C1-1									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
113.6 ft.	Tap Factory Made Active		8		0	<input type="checkbox"/>	6		
115.8 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C-1									




Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C1-1_C-1	Oliver Springs	Strutt St	Fibreglass Reinforc...	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
C1-1	115.8		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
C-1	115.8		8	8	N/A



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C1-1



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 113.6 ft. Grade: 0
Condition: Tap Factory Made Active
Remarks: N/A



Distance: 115.8 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C-1



Pipe Segment Refere... C1-1_C-1	City Oliver Springs	Street Strutt St	Material Fibreglass Reinforc...		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH C1-1	Total Length 115.8	Year Laid	Shape Circular		Location Details	
DS Manhole C-1	Length surveyed 115.8	Year Renewed	Height 8	Width 8	Pipe Joint... N/A	
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose		
QSR N/A	QMR N/A			Pre-Rehabilitation Survey		
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150727		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 07:31		Weather Dry	
Date Cleaned 20150727			End Time 07:39		Additional Info	

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
<div>Continuous Defects</div> <div><div>CodeIDLength</div><div></div></div>			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
			Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY			Pipe Rating	0		Pipe Rating	0		Overall Pipe Rating	0	
			Structural Index	0		O&M Index	0		Overall Index	0	
			Str. Quick Rating	0000		O&M Quick Rating	0000		Ovrl. Quick Rating	0000	