



## Defect Listing

Pipe Segment Refere... <b>C1-4_C1-3</b>	City <b>Oliver Springs</b>	Street <b>Bennett</b>	Material <b>Fibreglass Reinforc...</b>	Location C... <b>Light High...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>C1-4</b>	Total Length <b>229.4</b>	Year Laid	Shape <b>Circular</b>	Location Details	
DS Manhole <b>C1-3</b>	Length surveyed <b>229.4</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>N/A</b>


SPR <b>N/A</b>	MPR <b>N/A</b>	PO Number <b>4397-03</b>	Customer <b>GRW</b>
SPRI <b>N/A</b>	MPRI <b>N/A</b>	Work Order <b>4397-02</b>	Purpose <b>Pre-Rehabilitation Survey</b>
QSR <b>N/A</b>	QMR <b>N/A</b>		
OPR <b>N/A</b>	Surveyed By <b>Barry Rogers</b>	Direction <b>Downstream</b>	Date <b>20150724</b>
OPRI <b>N/A</b>	Certificate Number <b>U-1012-16405</b>	Pre-Cleaning <b>Jetting</b>	Time <b>09:12</b>
	Date Cleaned <b>20150724</b>	End Time <b>09:21</b>	Weather <b>Saturated</b>
			Additional Info <b>Mh C1-3 has been li...</b>

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C1-4									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
210.7 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
229.4 ft.	Water Level				5	<input type="checkbox"/>			
229.4 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C1-3									




## Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C1-4_C1-3	Oliver Springs	Bennett	Fibreglass Reinforc...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
C1-4	229.4		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
C1-3	229.4		8	8	N/A



Distance: 0.0 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: C1-4



Distance: 0.0 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 210.7 ft. Grade: 0  
Condition: Tap Factory Made  
Remarks: N/A




Distance: 229.4 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



## Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
<b>C1-4_C1-3</b>	<b>Oliver Springs</b>	<b>Bennett</b>	<b>Fibreglass Reinforc...</b>	<b>Light High...</b>	<b>Sanitary</b>
Upstream MH	Total Length	Year Laid	Shape	Location Details	
<b>C1-4</b>	<b>229.4</b>		<b>Circular</b>		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
<b>C1-3</b>	<b>229.4</b>		<b>8</b>	<b>8</b>	<b>N/A</b>



Distance: 229.4 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: C1-3



Pipe Segment Refere... C1-4_C1-3	City Oliver Springs	Street Bennett	Material Fibreglass Reinforc...		Location C... Light High...	Sewer Use Sanitary
Upstream MH C1-4	Total Length 229.4	Year Laid	Shape Circular		Location Details	
DS Manhole C1-3	Length surveyed 229.4	Year Renewed	Height 8	Width 8	Pipe Joint... N/A	
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose		
QSR N/A	QMR N/A			Pre-Rehabilitation Survey		
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150724		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 09:12		Weather Saturated	
Date Cleaned 20150724		End Time 09:21		Additional Info Mh C1-3 has been li...		

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
<div>Continuous Defects</div> <div>CodeIDLength</div>			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Subtotals			0		Subtotals	0		Subtotals	0		
SUMMARY			Pipe Rating	0	Pipe Rating	0	Overall Pipe Rating	0			
			Structural Index	0	O&M Index	0	Overall Index	0			
			Str. Quick Rating	0000	O&M Quick Rating	0000	Ovrl. Quick Rating	0000			