



Defect Listing

Pipe Segment Refere... C11-1_C-20	City Oliver Springs	Street Hwy 62	Material Concrete Pipe (non-...	Location C... Main Highw...	Sewer Use Sanitary
Upstream MH C11-1	Total Length 341.7	Year Laid	Shape Circular	Location Details	
DS Manhole C-20	Length surveyed 341.7	Year Renewed	Height 8	Width 8	Pipe Joint... 4


SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Upstream	Date 20150727	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 08:02	Weather Dry	
Date Cleaned 20150727			End Time 08:18	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C-20									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
339.9 ft.	Water Level				0	<input type="checkbox"/>			
341.7 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C11-1									




Image Report 4/Page


Pipe Segment Refere... C11-1_C-20	City Oliver Springs	Street Hwy 62	Material Concrete Pipe (non-...	Location C... Main Highw...	Sewer Use Sanitary
Upstream MH C11-1	Total Length 341.7	Year Laid	Shape Circular	Location Details	
DS Manhole C-20	Length surveyed 341.7	Year Renewed	Height 8	Width 8	Pipe Joint... 4



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C-20



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 339.9 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 341.7 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C11-1



PACP Conditions

Pipe Segment Refere... C11-1_C-20	City Oliver Springs	Street Hwy 62	Material Concrete Pipe (non-...	Location C... Main Highw...	Sewer Use Sanitary
Upstream MH C11-1	Total Length 341.7	Year Laid	Shape Circular	Location Details	
DS Manhole C-20	Length surveyed 341.7	Year Renewed	Height 8	Width 8	Pipe Joint... 4
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A	Direction Upstream		Date 20150727	
OPR N/A	Surveyed By Barry Rogers	Pre-Cleaning Jetting		Media label	
OPRI N/A	Certificate Number U-1012-16405	Time 08:02		Weather Dry	
Date Cleaned 20150727			End Time 08:18		Additional Info

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continuous Defects											
Code	ID	Length									
			Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY			Pipe Rating	0		Pipe Rating	0		Overall Pipe Rating	0	
			Structural Index	0		O&M Index	0		Overall Index	0	
			Str. Quick Rating	0000		O&M Quick Rating	0000		Ovrl. Quick Rating	0000	