

# **Defect Listing**

Pipe Segme	ent Refere	C	ity	Street	Mat	erial	Location C	Sewer Use	
C12-5_	_C12-4	Oliver	Springs	Hannah Dr	Concrete F	ipe (non	Light High	Sanitary	
Upstrea	am MH	Total	Length	Year Laid	Sha	ape	Location	n Details	
C1:	2-5	33	8.4		Circ	cular			
DS Ma	anhole	Length :	surveyed	Year Renewed	Height	Width Pipe Join			
C1:	C12-4		8.4		8	8	4		
SPR	N/A	MPR	2	PO Number			Customer		
CDDI	NI/A	MDDI		4397-03			GRW		
SPRI	N/A	MPRI	2	Work Order			Purpose		
QSR	N/A	QMR	2100	4397-02		Pre-I		urvey	
OF	PR	Surve	yed By	Direction	Date		Media label		
2	2		Rogers	Downstream	20150715				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
2	2		2-16405	Jetting	12:37		Dry		
		Date C	Cleaned	End Time		Additional Info			
(		2015	0715		13	:01			

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Po	Clock Position	
	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	C12-5								•
0.0 ft.	Water Level				5				
79.3 ft.	Tap Factory Made		6		0		9		
81.2 ft.	Water Level Sag				10				2
83.8 ft.	Tap Factory Made		6		0		3		
227.7 ft.	Tap Factory Made		6		0		9		
260.7 ft.	Tap Factory Made		6		0		9		
336.1 ft.	Water Level				5				
338.4 ft.	Access Point Manhole				0				
Remarks:	C12-4								•





#### **Image Report 4/Page**

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
C12-5_C12-4	Oliver Springs	Hannah Dr	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
C12-5	338.4		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
C12-4	338.4		8	8	4	



Distance: 0.0 ft. Grade: (

Condition: Access Point Manhole


Remarks: C12-5



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 79.3 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 81.2 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A





#### **Image Report 4/Page**


Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
C12-5_C12-4	Oliver Springs	Hannah Dr	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
C12-5	338.4		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
C12-4	338.4		8	8	4	



Distance: 83.8 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 227.7 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 260.7 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 336.1 ft. Grade: 0

Condition: Water Level

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



### Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
C12-5_C12-4	Oliver Springs	Hannah Dr	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
C12-5	338.4		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
C12-4	338.4		8	8	4	ر ا



Distance: 338.4 ft. Grade: 0

Condition: Access Point Manhole

Remarks: C12-4



## **PACP Conditions**

Pipe Segment Refere		C	ity	Street	Material		Location C	Sewer Use
C12-5	_C12-4	Oliver	Springs	Hannah Dr	Concrete F	ipe (non	Light High	Sanitary
Upstre	am MH	Total	Length	Year Laid	Shape		Location Details	
C1	2-5	33	8.4		Circ	cular		
DS M	anhole	Length s	surveyed	Year Renewed	Height	Width Pipe Joint		
C1	2-4	33	8.4		8	8	8 4	
SPR	N/A	MPR	2	PO Number			Customer	
0001	N1/A	MADDI		4397-03	4397-03			
SPRI	N/A	MPRI	2	Work Order		Purpose		
QSR	N/A	QMR	2100	4397-02		Pre-	Rehabilitation S	urvey
Ol	PR	Surve	yed By	Direction	Da	ate	Media	label
:	2	Barry_	Rogers	Downstream	20150715			
OF	OPRI		e Number	Pre-Cleaning	Time		Weather	
:	2 U-1012-16405		Jetting	12:37		Dry		
		Date C	Cleaned		End Time		Additional Info	
		2015	0715	13:01				

		Stru	Structural Ratings			& M Ratin	gs	Con	nbined Ra	tings
Normal [	Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
					4			4		_
		2	0	0	2	0	0	2	0	0
			0	0		1	2		1	2
		3	0	0	3	0	0	3	0	0
		4	0	0	4	0	0	4	0	0
		5	0	0	5	0	0	5	0	0
Continuou	s Defects									
Code I	D Length									
		<u> </u>								
		Subtotals	0		Subtotals	1		Subtotals	1	
SUMMARY		Pi	pe Rating	0	Pipe Rating		2	Overall Pipe Rating		2
		Struct	ural Index	0	0	&M Index	2.0	Ove	erall Index	2.0
		Str. Qu	ick Rating	0000	O&M Qui	ick Rating	2100	Ovrl. Qu	ick Rating	2100