



## Defect Listing

Pipe Segment Refere... <b>C13-1_C-21</b>	City <b>Oliver Springs</b>	Street <b>Browder Cir</b>	Material <b>Concrete Pipe (non-...</b>	Location C... <b>Light High...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>C13-1</b>	Total Length <b>215.3</b>	Year Laid	Shape <b>Circular</b>	Location Details	
DS Manhole <b>C-21</b>	Length surveyed <b>215.3</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>4</b>

SPR <b>N/A</b>	MPR <b>7</b>	PO Number <b>4397-03</b>	Customer <b>GRW</b>
SPRI <b>N/A</b>	MPRI <b>3.5</b>	Work Order <b>4397-02</b>	Purpose <b>Pre-Rehabilitation Survey</b>
QSR <b>N/A</b>	QMR <b>4131</b>		
OPR <b>7</b>	Surveyed By <b>Barry Rogers</b>	Direction <b>Downstream</b>	Date <b>20150715</b>
OPRI <b>3.5</b>	Certificate Number <b>U-1012-16405</b>	Pre-Cleaning <b>Jetting</b>	Time <b>09:52</b>
	Date Cleaned <b>20150715</b>	End Time <b>10:06</b>	Weather <b>Damp</b>
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C13-1									
0.0 ft.	Water Level				10	<input type="checkbox"/>			
5.0 ft.	Infiltration Runner				0	<input type="checkbox"/>	7		4
5.0 ft.	Infiltration Dripper				0	<input type="checkbox"/>	3		3
213.7 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	6		
214.9 ft.	Water Level				5	<input type="checkbox"/>			
215.3 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C-21									




## Image Report 4/Page


Pipe Segment Refere... <b>C13-1_C-21</b>	City <b>Oliver Springs</b>	Street <b>Browder Cir</b>	Material <b>Concrete Pipe (non-...</b>		Location C... <b>Light High...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>C13-1</b>	Total Length <b>215.3</b>	Year Laid	Shape <b>Circular</b>		Location Details	
DS Manhole <b>C-21</b>	Length surveyed <b>215.3</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>4</b>	



Distance: 0.0 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: C13-1



Distance: 0.0 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 5.0 ft. Grade: 4  
Condition: Infiltration Runner  
Remarks: N/A




Distance: 5.0 ft. Grade: 3  
Condition: Infiltration Dripper  
Remarks: N/A



## Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
<b>C13-1_C-21</b>	<b>Oliver Springs</b>	<b>Browder Cir</b>	<b>Concrete Pipe (non-...</b>	<b>Light High...</b>	<b>Sanitary</b>
<b>Upstream MH</b>	Total Length	Year Laid	<b>Shape</b>	Location Details	
<b>C13-1</b>	<b>215.3</b>		<b>Circular</b>		
<b>DS Manhole</b>	<b>Length surveyed</b>	Year Renewed	<b>Height</b>	Width	Pipe Joint...
<b>C-21</b>	<b>215.3</b>		<b>8</b>	<b>8</b>	<b>4</b>



Distance: 213.7 ft. Grade: 0  
Condition: Tap Factory Made  
Remarks: N/A



Distance: 214.9 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 215.3 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: C-21



## Albuquerque, NM

[illegible]