505-341-0109



Defect Listing

Pipe Segment Refere		City		Street	Mat	erial	Location C	Sewer Use	
C14-1	_C-23 Oliver Springs Edmonds Dr Fibreglass Re		ass Reinforc Yard		Sanitary				
Upstream MH		Total Length		Year Laid	Shape		Location Details		
C1	4-1	310	0.9		Circ	cular			
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint		
C-	-23	310.9			8	8	N/A		
SPR	N/A	MPR	N/A	PO Number			Customer		
				4397-03		GRW			
SPRI	N/A	MPRI	N/A	Work Order	Work Order		Purpose		
QSR	N/A	QMR	N/A	4397-02		Pre-	Rehabilitation S	habilitation Survey	
OI	PR	Surve	/ed By	Direction	Da	ate	Media	alabel	
N.	/A	Barry_	Rogers	Downstream	2015	0714			
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
N.	N/A U-1012-16405		-16405	Jetting 1		11:26			
Date Cleaned 20150714						End Time		Additional Info	
					11	:46			


Distance	Condition	Cont. Dfct.	Values				Clock Position		Cuada
Distance	Condition		1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	C14-1								
0.0 ft.	Water Level				10				
43.9 ft.	Tap Factory Made Active		6		0		3		
165.9 ft.	Tap Factory Made		6		0		3		
274.4 ft.	Tap Factory Made		6		0		9		
308.8 ft.	Water Level				5				
310.9 ft.	Access Point Manhole				0				
Remarks:	C-23								





Image Report 4/Page


Pipe Segment Refere	City	Street	Mat	erial	Location C	Sewer Use
C14-1_C-23	Oliver Springs	Edmonds Dr	Fibreglass Reinforc		Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
C14-1	310.9		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
C-23	310.9		8	8	N/A	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: C14-1



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 43.9 ft. **Grade**: 0 **Condition**: Tap Factory Made Active

Remarks: N/A



Distance: 165.9 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A





Image Report 4/Page

$\overline{}$	Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
	C14-1_C-23	Oliver Springs	Edmonds Dr	Fibreglass Reinforc		Yard	Sanitary
	Upstream MH	Total Length	Year Laid	Shape		Location	Details
	C14-1	310.9		Circular			
	DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
	C-23	310.9		8	8	N/A	ر ا



Distance: 274.4 ft. Grade:

Condition: Tap Factory Made

Remarks: N/A



Distance: 308.8 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 310.9 ft. Grade: Condition:

Access Point Manhole

Remarks: C-23



PACP Conditions

Pipe Segment Refere		Ci	ity	Street	Mat	erial	Location C	Sewer Use
C14-1	_C-23	Oliver S	Springs	Edmonds Dr	Fibreglass	Fibreglass Reinforc		Sanitary
Upstrea	am MH	Total L	ength	Year Laid	Sha	ape	Location	n Details
C14	4-1	310	0.9		Circ	ular		
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint	
C-:	23	310	0.9		8	8	N/A	
SPR	N/A	MPR	N/A	PO Number			Customer	
SPRI	N/A	MPRI	N/A	4397-03			GRW	
0110	19/5	IVII TXI	19/5	Work Order				
QSR	N/A	QMR	N/A	4397-02		Pre-	Rehabilitation Survey	
OF	PR	Surveyed By		Direction	Da	Date		a label
N/	' A	Barry_l	Rogers	Downstream	2015	0714		
OF	OPRI		e Number	Pre-Cleaning	Time		Weather	
N/	N/A		-16405	Jetting	11	:26	Light Rain	
		Date C	leaned		End	End Time		nal Info
		2015	0714		11:46			

		Structural Ratings			0	& M Ratin	gs	Con	nbined Ra	tings
Normal [Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
		4			4			4		_
		2	0	0	2	0	0	2	0	0
			0	0		0	0		0	0
		3	0	0	3	0	0	3	0	0
		4	0	0	4	0	0	4	0	0
		5	0	0	5	0	0	5	0	0
Continuou	s Defects									
Code II	D Length									
		Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY		 Pi	pe Rating	0	 Pi	pe Rating	0	Overall P	pe Rating	0
		Struct	ural Index	0	0	&M Index	0	Ove	erall Index	0
		Str. Qu	ick Rating	0000	O&M Qui	ick Rating	0000	Ovrl. Qu	ick Rating	0000