



Defect Listing

Pipe Segment Refere... C14-6_C14-5	City Oliver Springs	Street richards dr	Material Fibreglass Reinforc...	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH C14-6	Total Length 284.7	Year Laid	Shape Circular	Location Details t	
DS Manhole C14-5	Length surveyed 284.7	Year Renewed	Height 8	Width 8	Pipe Joint... N/A

SPR N/A	MPR 2	PO Number 4397-03	Customer GRW
SPRI N/A	MPRI 2	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR N/A	QMR 2100		
OPR 2	Surveyed By Barry Rogers	Direction Downstream	Date 20150716
OPRI 2	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 08:59
	Date Cleaned 20150716	End Time 09:27	Weather Dry
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: c14-6									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
88.8 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
156.4 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
191.9 ft.	Water Level Sag				10	<input type="checkbox"/>			2
211.0 ft.	Tap Factory Made Active		6		0	<input type="checkbox"/>	9		
233.6 ft.	Tap Factory Made Active		6		0	<input type="checkbox"/>	3		
283.6 ft.	Water Level				5	<input type="checkbox"/>			
284.7 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: c14-5									



Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C14-6_C14-5	Oliver Springs	richards dr	Fibreglass Reinforc...	Easement/R...	Sanitary
Upstream MH C14-6	Total Length 284.7	Year Laid	Shape Circular	Location Details t	
DS Manhole C14-5	Length surveyed 284.7	Year Renewed	Height 8	Width 8	Pipe Joint... N/A




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: c14-6



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 88.8 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 156.4 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C14-6_C14-5	Oliver Springs	richards dr	Fibreglass Reinforc...	Easement/R...	Sanitary
Upstream MH C14-6	Total Length 284.7	Year Laid	Shape Circular	Location Details t	
DS Manhole C14-5	Length surveyed 284.7	Year Renewed	Height 8	Width 8	Pipe Joint... N/A



Distance: 191.9 ft. Grade: 2
Condition: Water Level Sag
Remarks: N/A



Distance: 211.0 ft. Grade: 0
Condition: Tap Factory Made Active
Remarks: N/A



Distance: 233.6 ft. Grade: 0
Condition: Tap Factory Made Active
Remarks: N/A



Distance: 283.6 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere... C14-6_C14-5	City Oliver Springs	Street richards dr	Material Fibreglass Reinforc...		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH C14-6	Total Length 284.7	Year Laid	Shape Circular		Location Details t	
DS Manhole C14-5	Length surveyed 284.7	Year Renewed	Height 8	Width 8	Pipe Joint...	N/A



Distance: 284.7 ft. Grade: 0
Condition: Access Point Manhole
Remarks: c14-5



Pipe Segment Refere... C14-6_C14-5	City Oliver Springs	Street richards dr	Material Fibreglass Reinforc...		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH C14-6	Total Length 284.7	Year Laid	Shape Circular		Location Details t	
DS Manhole C14-5	Length surveyed 284.7	Year Renewed	Height 8	Width 8	Pipe Joint... N/A	
SPR N/A	MPR 2	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI 2	Work Order 4397-02		Purpose		
QSR N/A	QMR 2100			Pre-Rehabilitation Survey		
OPR 2	Surveyed By Barry_Rogers	Direction Downstream	Date 20150716		Media label	
OPRI 2	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 08:59		Weather Dry	
Date Cleaned 20150716			End Time 09:27		Additional Info	

Page #: 5