



## Defect Listing

Pipe Segment Refere... <b>C14-7_C14-6</b>	City <b>Oliver Springs</b>	Street <b>richards dr</b>	Material <b>Fibreglass Reinforc...</b>	Location C... <b>Easement/R...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>C14-7</b>	Total Length <b>181.3</b>	Year Laid	Shape <b>Circular</b>	Location Details	
DS Manhole <b>C14-6</b>	Length surveyed <b>181.3</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>N/A</b>


SPR <b>N/A</b>	MPR <b>N/A</b>	PO Number <b>4397-03</b>	Customer <b>GRW</b>
SPRI <b>N/A</b>	MPRI <b>N/A</b>	Work Order <b>4397-02</b>	Purpose <b>Pre-Rehabilitation Survey</b>
QSR <b>N/A</b>	QMR <b>N/A</b>		
OPR <b>N/A</b>	Surveyed By <b>Barry Rogers</b>	Direction <b>Downstream</b>	Date <b>20150716</b>
OPRI <b>N/A</b>	Certificate Number <b>U-1012-16405</b>	Pre-Cleaning <b>Jetting</b>	Time <b>08:20</b>
	Date Cleaned <b>20150716</b>	End Time <b>08:47</b>	Weather <b>Dry</b>
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: c14-7									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
32.7 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
167.4 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
178.5 ft.	Water Level				5	<input type="checkbox"/>			
181.3 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: c14-6									




## Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
<b>C14-7_C14-6</b>	<b>Oliver Springs</b>	<b>richards dr</b>	<b>Fibreglass Reinforc...</b>	<b>Easement/R...</b>	<b>Sanitary</b>
<b>Upstream MH</b>	Total Length	Year Laid	<b>Shape</b>	Location Details	
<b>C14-7</b>	<b>181.3</b>		<b>Circular</b>		
<b>DS Manhole</b>	<b>Length surveyed</b>	Year Renewed	<b>Height</b>	Width	Pipe Joint...
<b>C14-6</b>	<b>181.3</b>		<b>8</b>	<b>8</b>	<b>N/A</b>




Distance: 0.0 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: c14-7



Distance: 0.0 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 32.7 ft. Grade: 0  
Condition: Tap Factory Made  
Remarks: N/A




Distance: 167.4 ft. Grade: 0  
Condition: Tap Factory Made  
Remarks: N/A




## Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
<b>C14-7_C14-6</b>	<b>Oliver Springs</b>	<b>richards dr</b>	<b>Fibreglass Reinf...</b>	<b>Easement/R...</b>	<b>Sanitary</b>
<b>Upstream MH</b>	Total Length	Year Laid	<b>Shape</b>	Location Details	
<b>C14-7</b>	<b>181.3</b>		<b>Circular</b>		
<b>DS Manhole</b>	<b>Length surveyed</b>	Year Renewed	<b>Height</b>	Width	Pipe Joint...
<b>C14-6</b>	<b>181.3</b>		<b>8</b>	<b>8</b>	<b>N/A</b>



Distance: 178.5 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 181.3 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: c14-6



## PACP Conditions

Pipe Segment Refere... <b>C14-7_C14-6</b>	City <b>Oliver Springs</b>	Street <b>richards dr</b>	Material <b>Fibreglass Reinforc...</b>	Location C... <b>Easement/R...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>C14-7</b>	Total Length <b>181.3</b>	Year Laid	Shape <b>Circular</b>	Location Details	
DS Manhole <b>C14-6</b>	Length surveyed <b>181.3</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>N/A</b>
SPR <b>N/A</b>	MPR <b>N/A</b>	PO Number <b>4397-03</b>		Customer <b>GRW</b>	
SPRI <b>N/A</b>	MPRI <b>N/A</b>	Work Order <b>4397-02</b>		Purpose <b>Pre-Rehabilitation Survey</b>	
QSR <b>N/A</b>	QMR <b>N/A</b>	Direction <b>Downstream</b>		Date <b>20150716</b>	
OPR <b>N/A</b>	Surveyed By <b>Barry Rogers</b>	Pre-Cleaning <b>Jetting</b>		Media label	
OPRI <b>N/A</b>	Certificate Number <b>U-1012-16405</b>	Time <b>08:20</b>		Weather <b>Dry</b>	
Date Cleaned <b>20150716</b>			End Time <b>08:47</b>		Additional Info

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continuous Defects											
Code	ID	Length									
			Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY			Pipe Rating	0		Pipe Rating	0		Overall Pipe Rating	0	
			Structural Index	0		O&M Index	0		Overall Index	0	
			Str. Quick Rating	0000		O&M Quick Rating	0000		Ovrl. Quick Rating	0000	