



Defect Listing

Pipe Segment Refere... C15-6_C15-5	City Oliver Springs	Street HWy 62	Material PolyVinyl Chloride	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH C15-6	Total Length 193.2	Year Laid	Shape Circular	Location Details	
DS Manhole C15-5	Length surveyed 193.2	Year Renewed	Height 8	Width 8	Pipe Joint... 13


SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150727	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 08:44	Weather Dry	
Date Cleaned 20150727			End Time 08:53	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C15-6									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
120.9 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	2		
193.2 ft.	Water Level				5	<input type="checkbox"/>			
193.2 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C15-5									



Image Report 4/Page

Pipe Segment Refere... C15-6_C15-5	City Oliver Springs	Street HWy 62	Material PolyVinyl Chloride		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH C15-6	Total Length 193.2	Year Laid	Shape Circular		Location Details	
DS Manhole C15-5	Length surveyed 193.2	Year Renewed	Height 8	Width 8	Pipe Joint...	13



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C15-6



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 120.9 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 193.2 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere... C15-6_C15-5	City Oliver Springs	Street HWy 62	Material PolyVinyl Chloride		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH C15-6	Total Length 193.2	Year Laid	Shape Circular		Location Details	
DS Manhole C15-5	Length surveyed 193.2	Year Renewed	Height 8	Width 8	Pipe Joint...	13



Distance: 193.2 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C15-5



PACP Conditions

Pipe Segment Refere... C15-6_C15-5	City Oliver Springs	Street HWy 62	Material PolyVinyl Chloride	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH C15-6	Total Length 193.2	Year Laid	Shape Circular	Location Details	
DS Manhole C15-5	Length surveyed 193.2	Year Renewed	Height 8	Width 8	Pipe Joint... 13
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A	Direction Downstream		Date 20150727	
OPR N/A	Surveyed By Barry Rogers	Pre-Cleaning Jetting		Media label	
OPRI N/A	Certificate Number U-1012-16405	Time 08:44		Weather Dry	
Date Cleaned 20150727			End Time 08:53		Additional Info

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code	ID	Length									
							</				