



Defect Listing

Pipe Segment Refere... C2-1A_C-9	City Oliver Springs	Street Bennett	Material Fibreglass Reinforc...	Location C... Light High...	Sewer Use Sanitary
Upstream MH C2-1A	Total Length 154.7	Year Laid	Shape Circular	Location Details	
DS Manhole C-9	Length surveyed 154.7	Year Renewed	Height 8	Width 8	Pipe Joint... N/A


SPR N/A	MPR 7	PO Number 4397-03	Customer GRW
SPRI N/A	MPRI 3.5	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR N/A	QMR 4131		
OPR 7	Surveyed By Barry Rogers	Direction Downstream	Date 20150723
OPRI 3.5	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 10:49
	Date Cleaned 20150723	End Time 10:56	Weather Heavy Rain
			Media label Mh C-9N1 is buried ...

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C-9N1									
0.0 ft.	Water Level				10	<input type="checkbox"/>			
133.0 ft.	Water Level Sag				35	<input type="checkbox"/>			3
151.1 ft.	Camera Underwater				0	<input type="checkbox"/>			4
154.7 ft.	Survey Abandoned				0	<input type="checkbox"/>			
Remarks: MCU cannot see to Continue									




Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C2-1A_C-9	Oliver Springs	Bennett	Fibreglass Reinforc...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
C2-1A	154.7		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
C-9	154.7		8	8	N/A



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C-9N1



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 133.0 ft. Grade: 3
Condition: Water Level Sag
Remarks: N/A




Distance: 151.1 ft. Grade: 4
Condition: Camera Underwater
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C2-1A_C-9	Oliver Springs	Bennett	Fibreglass Reinforc...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
C2-1A	154.7		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
C-9	154.7		8	8	N/A



Distance: 154.7 ft. Grade: 0
Condition: Survey Abandoned
Remarks: MCU cannot see to Continue



PACP Conditions

Pipe Segment Refere... C2-1A_C-9	City Oliver Springs	Street Bennett	Material Fibreglass Reinforc...		Location C... Light High...	Sewer Use Sanitary
Upstream MH C2-1A	Total Length 154.7	Year Laid	Shape Circular		Location Details	
DS Manhole C-9	Length surveyed 154.7	Year Renewed	Height 8	Width 8	Pipe Joint... N/A	
SPR N/A	MPR 7	PO Number 4397-03			Customer GRW	
SPRI N/A	MPRI 3.5	Work Order			Purpose	
QSR N/A	QMR 4131	4397-02			Pre-Rehabilitation Survey	
OPR 7	Surveyed By Barry_Rogers	Direction Downstream	Date 20150723		Media label	
OPRI 3.5	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 10:49		Weather Heavy Rain	
Date Cleaned 20150723			End Time 10:56		Additional Info Mh C-9N1 is buried ...	

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	1	3	3	1	3
			4	0	0	4	1	4	4	1	4
			5	0	0	5	0	0	5	0	0
Code	ID	Length									