



## Defect Listing

Pipe Segment Refere... <b>C3-1_C-9</b>	City <b>Oliver Springs</b>	Street <b>Heneley Circle</b>	Material <b>Concrete Pipe (non-...</b>	Location C... <b>Light High...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>C3-1</b>	Total Length <b>344.4</b>	Year Laid	Shape <b>Circular</b>	Location Details	
DS Manhole <b>C-9</b>	Length surveyed <b>344.4</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>4</b>


SPR <b>N/A</b>	MPR <b>N/A</b>	PO Number <b>4397-03</b>		Customer <b>GRW</b>	
SPRI <b>N/A</b>	MPRI <b>N/A</b>	Work Order <b>4397-02</b>		Purpose <b>Pre-Rehabilitation Survey</b>	
QSR <b>N/A</b>	QMR <b>N/A</b>				
OPR <b>N/A</b>	Surveyed By <b>Barry Rogers</b>	Direction <b>Downstream</b>	Date <b>20150723</b>	Media label	
OPRI <b>N/A</b>	Certificate Number <b>U-1012-16405</b>	Pre-Cleaning <b>Jetting</b>	Time <b>08:57</b>	Weather <b>Saturated</b>	
Date Cleaned <b>20150723</b>			End Time <b>09:10</b>	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C3-1									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
85.2 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
342.6 ft.	Water Level				5	<input type="checkbox"/>			
342.8 ft.	Infiltration Stain				0	<input type="checkbox"/>	7	5	
344.4 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C-9									




## Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C3-1_C-9	Oliver Springs	Heneley Circle	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
C3-1	344.4		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
C-9	344.4		8	8	4




Distance: 0.0 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: C3-1



Distance: 0.0 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 85.2 ft. Grade: 0  
Condition: Tap Factory Made  
Remarks: N/A




Distance: 342.6 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



## Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C3-1_C-9	Oliver Springs	Heneley Circle	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
C3-1	344.4		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
C-9	344.4		8	8	4



Distance: 342.8 ft. Grade: 0  
Condition: Infiltration Stain  
Remarks: N/A



Distance: 344.4 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: C-9



## PACP Conditions

Pipe Segment Refere... <b>C3-1_C-9</b>	City <b>Oliver Springs</b>	Street <b>Heneley Circle</b>	Material <b>Concrete Pipe (non-...</b>	Location C... <b>Light High...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>C3-1</b>	Total Length <b>344.4</b>	Year Laid	Shape <b>Circular</b>	Location Details	
DS Manhole <b>C-9</b>	Length surveyed <b>344.4</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>4</b>
SPR <b>N/A</b>	MPR <b>N/A</b>	PO Number <b>4397-03</b>		Customer <b>GRW</b>	
SPRI <b>N/A</b>	MPRI <b>N/A</b>	Work Order <b>4397-02</b>		Purpose <b>Pre-Rehabilitation Survey</b>	
QSR <b>N/A</b>	QMR <b>N/A</b>	Direction <b>Downstream</b>		Date <b>20150723</b>	
OPR <b>N/A</b>	Surveyed By <b>Barry Rogers</b>	Pre-Cleaning <b>Jetting</b>		Media label	
OPRI <b>N/A</b>	Certificate Number <b>U-1012-16405</b>	Time <b>08:57</b>		Weather <b>Saturated</b>	
Date Cleaned <b>20150723</b>			End Time <b>09:10</b>		Additional Info

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continuous Defects											
Code	ID	Length									
			Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY			Pipe Rating	0		Pipe Rating	0		Overall Pipe Rating	0	
			Structural Index	0		O&M Index	0		Overall Index	0	
			Str. Quick Rating	0000		O&M Quick Rating	0000		Ovrl. Quick Rating	0000	