



Defect Listing

Pipe Segment Refere... C3-3_C3-2	City Oliver Springs	Street Henley Circle	Material Fibreglass Reinforc...	Location C... Light High...	Sewer Use Sanitary
Upstream MH C3-3	Total Length 227.9	Year Laid	Shape Circular	Location Details	
DS Manhole C3-2	Length surveyed 227.9	Year Renewed	Height 8	Width 8	Pipe Joint... N/A


SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150723	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 08:24	Weather Saturated	
Date Cleaned 20150723			End Time 08:35	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C3-3									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
86.0 ft.	Tap Factory Made Active		6		0	<input type="checkbox"/>	9		
155.3 ft.	Tap Factory Made Active		6		0	<input type="checkbox"/>	9		
224.6 ft.	Water Level				5	<input type="checkbox"/>			
227.9 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C3-2									




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C3-3_C3-2	Oliver Springs	Henley Circle	Fibreglass Reinforc...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
C3-3	227.9		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
C3-2	227.9		8	8	N/A




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C3-3



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 86.0 ft. Grade: 0
Condition: Tap Factory Made Active
Remarks: N/A



Distance: 155.3 ft. Grade: 0
Condition: Tap Factory Made Active
Remarks: N/A




Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C3-3_C3-2	Oliver Springs	Henley Circle	Fibreglass Reinforc...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
C3-3	227.9		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
C3-2	227.9		8	8	N/A



Distance: 224.6 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 227.9 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C3-2



Pipe Segment Refere... C3-3_C3-2	City Oliver Springs	Street Henley Circle	Material Fibreglass Reinforc...		Location C... Light High...	Sewer Use Sanitary
Upstream MH C3-3	Total Length 227.9	Year Laid	Shape Circular		Location Details	
DS Manhole C3-2	Length surveyed 227.9	Year Renewed	Height 8	Width 8	Pipe Joint... N/A	
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose		
QSR N/A	QMR N/A			Pre-Rehabilitation Survey		
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150723		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 08:24		Weather Saturated	
Date Cleaned 20150723			End Time 08:35		Additional Info	

Page #: 4