



Defect Listing

Pipe Segment Refere... C5-11_C5-10	City Oliver Springs	Street Strutt	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH C5-11	Total Length 225.5	Year Laid	Shape Circular	Location Details 184	
DS Manhole C5-10	Length surveyed 225.5	Year Renewed	Height 8	Width 8	Pipe Joint... 4


SPR N/A	MPR N/A	PO Number 4397-03	Customer GRW
SPRI N/A	MPRI N/A	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR N/A	QMR N/A		
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150722
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 06:29
	Date Cleaned 20150722	End Time 06:44	Weather Dry
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C5-11									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
21.7 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
103.0 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
224.1 ft.	Tap Factory Made		8		0	<input type="checkbox"/>	6		
225.5 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C5-10									




Image Report 4/Page


Pipe Segment Refere... C5-11_C5-10	City Oliver Springs	Street Strutt	Material Concrete Pipe (non-...		Location C... Light High...	Sewer Use Sanitary
Upstream MH C5-11	Total Length 225.5	Year Laid	Shape Circular		Location Details 184	
DS Manhole C5-10	Length surveyed 225.5	Year Renewed	Height 8	Width 8	Pipe Joint... 4	




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C5-11



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 21.7 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Distance: 103.0 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Image Report 4/Page

Pipe Segment Refere... C5-11_C5-10	City Oliver Springs	Street Strutt	Material Concrete Pipe (non-...		Location C... Light High...	Sewer Use Sanitary
Upstream MH C5-11	Total Length 225.5	Year Laid	Shape Circular		Location Details 184	
DS Manhole C5-10	Length surveyed 225.5	Year Renewed	Height 8	Width 8	Pipe Joint... 4	



Distance: 224.1 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 225.5 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C5-10



Pipe Segment Refere... C5-11_C5-10	City Oliver Springs	Street Strutt	Material Concrete Pipe (non-...		Location C... Light High...	Sewer Use Sanitary
Upstream MH C5-11	Total Length 225.5	Year Laid	Shape Circular		Location Details 184	
DS Manhole C5-10	Length surveyed 225.5	Year Renewed	Height 8	Width 8	Pipe Joint... 4	
SPR N/A	MPR N/A	PO Number 4397-03			Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02			Purpose	
QSR N/A	QMR N/A				Pre-Rehabilitation Survey	
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150722		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 06:29		Weather Dry	
Date Cleaned 20150722			End Time 06:44		Additional Info	

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code	ID	Length									
			Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY			Pipe Rating	0		Pipe Rating	0		Overall Pipe Rating	0	
			Structural Index	0		O&M Index	0		Overall Index	0	
			Str. Quick Rating	0000		O&M Quick Rating	0000		Ovrl. Quick Rating	0000	