



Defect Listing

Pipe Segment Refere... C5-15_C5-14	City Oliver Springs	Street Cherokee Place	Material PolyVinyl Chloride	Location C... Light High...	Sewer Use Sanitary
Upstream MH C5-15	Total Length 151	Year Laid	Shape Circular	Location Details Apartment Complex	
DS Manhole C5-14	Length surveyed 151	Year Renewed	Height 8	Width 8	Pipe Joint... 13


SPR 2	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI 2	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR 2100	QMR N/A				
OPR 2	Surveyed By Barry Rogers	Direction Downstream	Date 20150721	Media label	
OPRI 2	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 09:52	Weather Damp	
Date Cleaned 20150721			End Time 09:59	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C5-15									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
111.1 ft.	Joint Offset Large				0	<input type="checkbox"/>			2
147.7 ft.	Water Level				5	<input type="checkbox"/>			
151.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C5-14									




Image Report 4/Page

Pipe Segment Refere... C5-15_C5-14	City Oliver Springs	Street Cherokee Place	Material PolyVinyl Chloride		Location C... Light High...	Sewer Use Sanitary
Upstream MH C5-15	Total Length 151	Year Laid	Shape Circular		Location Details Apartment Complex	
DS Manhole C5-14	Length surveyed 151	Year Renewed	Height 8	Width 8	Pipe Joint... 13	




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C5-15



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 111.1 ft. Grade: 2
Condition: Joint Offset Large
Remarks: N/A



Distance: 147.7 ft. Grade: 0
Condition: Water Level
Remarks: N/A




Image Report 4/Page

Pipe Segment Refere... C5-15_C5-14	City Oliver Springs	Street Cherokee Place	Material PolyVinyl Chloride		Location C... Light High...	Sewer Use Sanitary
Upstream MH C5-15	Total Length 151	Year Laid	Shape Circular		Location Details Apartment Complex	
DS Manhole C5-14	Length surveyed 151	Year Renewed	Height 8	Width 8	Pipe Joint... 13	



Distance: 151.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C5-14



Pipe Segment Refere... C5-15_C5-14	City Oliver Springs	Street Cherokee Place	Material PolyVinyl Chloride		Location C... Light High...	Sewer Use Sanitary
Upstream MH C5-15	Total Length 151	Year Laid	Shape Circular		Location Details Apartment Complex	
DS Manhole C5-14	Length surveyed 151	Year Renewed	Height 8	Width 8	Pipe Joint... 13	
SPR 2	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI 2	MPRI N/A	Work Order 4397-02		Purpose		
QSR 2100	QMR N/A			Pre-Rehabilitation Survey		
OPR 2	Surveyed By Barry_Rogers	Direction Downstream	Date 20150721		Media label	
OPRI 2	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 09:52		Weather Damp	
Date Cleaned 20150721			End Time 09:59		Additional Info	

Page #: 4