

Defect Listing

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
C5-4A_C5-4		Oliver Springs		McGhee St	Concrete F	Concrete Pipe (non		Sanitary	
Upstream MH		Total Length		Year Laid	Sha	ape	Location Details		
C5-	C5-4A 174.1			Circ	ular				
DS Ma	anhole	Length s	urveyed	Year Renewed	Height	Width	idth Pipe Joint		
C5-4		174.1			8	8	4		
SPR	N/A	MPR	N/A	PO Number			Customer		
0001				4397-03		GRW			
SPRI	N/A	MPRI	N/A	Work Order					
QSR	N/A	QMR	N/A	4397-02		Pre-l	e-Rehabilitation Survey		
O	PR	Surveyed By		Direction	Date		Media label		
N.	/A	Barry_Rogers		Downstream	20150812				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
N/A		U-1012-16405		No Pre-Cleaning	14:36		Dry		
		Date C	leaned		End Time		Additional Info		
					14	:52			

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Overde
Distance	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	C5-4A								
0.0 ft.	Water Level				5				
34.2 ft.	Tap Factory Made		6		0		3		
173.7 ft.	Water Level				5				
174.1 ft.	Access Point Manhole				0				
Remarks:	C5-4								•





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
C5-4A_C5-4	Oliver Springs	McGhee St	Concrete Pipe (non		Woods	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
C5-4A	174.1		Circular			
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
C5-4	174.1		8	8	4	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole


Remarks: C5-4A



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 34.2 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 173.7 ft. Grade: 0

Condition: Water Level

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
C5-4A_C5-4	Oliver Springs	McGhee St	Concrete Pipe (non		Woods	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
C5-4A	174.1		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
C5-4	174.1		8	8	4	



Distance: 174.1 ft. Grade: 0

Condition: Access Point Manhole

Remarks: C5-4



PACP Conditions

Pipe Segme	ent Refere	City		Street	Mat	erial	Location C	Sewer Use	
C5-4A	_C5-4	Oliver	Springs	McGhee St	Concrete P	ipe (non	Sanitary		
Upstre	am MH	Total I	Length	Year Laid	Shape		Location Details		
C5	-4A	17	4.1		Circ	ular	ar		
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Width Pipe Joint		
C!	5-4	17	4.1		8	8	8 4		
SPR	N/A	MPR	N/A	PO Number		Customer			
ODDI	NI/A	MADDI	N1/A	4397-03			GRW Purpose		
SPRI	N/A	MPRI	N/A	Work Order					
QSR	N/A	QMR	N/A	4397-02		Pre-F	Rehabilitation Survey		
OI	PR .	Surveyed By		Direction	Date		Media label		
N.	/A	Barry_Rogers		Downstream	20150812				
OPRI		Certificate Number		Pre-Cleaning	Time		Weather		
N/A		U-1012-16405		No Pre-Cleaning 14		:36	Dry		
		Date C	Cleaned	End Time		Additional Info			
				14					

	Structural Ratings			0	& M Ratin	gs	Con	nbined Ra	tings
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
	,								
	1	0	0	1	0	0	1	0	0
	2	0	0	2	0	0	2	0	0
	3	0	0	3	0	0	3	0	0
	4	0	0	4	0	0	4	0	0
	5	0	0	5	0	0	5	0	0
Continuous Defects Code ID Length									
	Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY	Struct	ipe Rating ural Index	0 0	0	pe Rating	0 0	Ove	ipe Rating erall Index	0 0
	Str. Qu	ick Rating	0000	U&IVI QU	ick Rating	0000	Ovri. Qu	ick Rating	0000