



Defect Listing

Pipe Segment Refere... C5-6_C5-5	City Oliver Springs	Street Mcghee St	Material Fibreglass Reinforc...	Location C... Woods	Sewer Use Sanitary
Upstream MH C5-6	Total Length 265.3	Year Laid	Shape Circular	Location Details	
DS Manhole C5-5	Length surveyed 265.3	Year Renewed	Height 8	Width 8	Pipe Joint... N/A

SPR N/A	MPR N/A	PO Number 4397-03	Customer GRW
SPRI N/A	MPRI N/A	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR N/A	QMR N/A		
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150812
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning No Pre-Cleaning	Time 13:44
	Date Cleaned	End Time 14:06	Weather Dry
		Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C5-6									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
155.7 ft.	Tap Factory Made		4		0	<input type="checkbox"/>	3		
265.3 ft.	Lining Failure Other				0	<input type="checkbox"/>	7	5	
Remarks: LINING HAVE NOT BEEN CAT OUT OF MANHOLE									
265.3 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C5-5									




Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C5-6_C5-5	Oliver Springs	Mcghee St	Fibreglass Reinforc...	Woods	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
C5-6	265.3		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
C5-5	265.3		8	8	N/A




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C5-6



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 155.7 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 265.3 ft. Grade: 0
Condition: Lining Failure Other
Remarks: LINING HAVE NOT BEEN CAT OUT OF MANHOLE




Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C5-6_C5-5	Oliver Springs	Mcghee St	Fibreglass Reinforc...	Woods	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
C5-6	265.3		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
C5-5	265.3		8	8	N/A



Distance: 265.3 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C5-5



Pipe Segment Refere... C5-6_C5-5	City Oliver Springs	Street Mcghee St	Material Fibreglass Reinforc...		Location C... Woods	Sewer Use Sanitary
Upstream MH C5-6	Total Length 265.3	Year Laid	Shape Circular		Location Details	
DS Manhole C5-5	Length surveyed 265.3	Year Renewed	Height 8	Width 8	Pipe Joint... N/A	
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose		
QSR N/A	QMR N/A			Pre-Rehabilitation Survey		
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150812		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning No Pre-Cleaning	Time 13:44		Weather Dry	
Date Cleaned			End Time 14:06		Additional Info	

Page #: 4