



Defect Listing

Pipe Segment Refere... C5-7_C5-6	City Oliver Springs	Street Mcghee St	Material Fibreglass Reinforc...	Location C... Light High...	Sewer Use Sanitary
Upstream MH C5-7	Total Length 187.2	Year Laid	Shape Circular	Location Details	
DS Manhole C5-6	Length surveyed 187.2	Year Renewed	Height 8	Width 8	Pipe Joint... N/A


SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150722	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 08:27	Weather Dry	
Date Cleaned 20150722			End Time 08:32	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C5-7									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
184.0 ft.	Water Level				5	<input type="checkbox"/>			
187.2 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C5-6									




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C5-7_C5-6	Oliver Springs	Mcghee St	Fibreglass Reinforc...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
C5-7	187.2		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
C5-6	187.2		8	8	N/A



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C5-7



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 184.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 187.2 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C5-6



PACP Conditions

Pipe Segment Refere... C5-7_C5-6	City Oliver Springs	Street Mcghee St	Material Fibreglass Reinforc...		Location C... Light High...	Sewer Use Sanitary
Upstream MH C5-7	Total Length 187.2	Year Laid	Shape Circular		Location Details	
DS Manhole C5-6	Length surveyed 187.2	Year Renewed	Height 8	Width 8	Pipe Joint... N/A	
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose		
QSR N/A	QMR N/A			Pre-Rehabilitation Survey		
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150722		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 08:27		Weather Dry	
Date Cleaned 20150722			End Time 08:32		Additional Info	

[illegible]