



Defect Listing

Pipe Segment Refere... C6-1_C5-14	City Oliver Springs	Street Cherokee Place	Material PolyVinyl Chloride		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH C6-1	Total Length 303.5	Year Laid	Shape Circular		Location Details Apartment Complex	
DS Manhole C5-14	Length surveyed 303.5	Year Renewed	Height 8	Width 8	Pipe Joint... 13	


SPR 3	MPR 2	PO Number 4397-03		Customer GRW	
SPRI 3	MPRI 2	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR 3100	QMR 2100				
OPR 5	Surveyed By Barry Rogers	Direction Downstream	Date 20150721	Media label	
OPRI 2.5	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 10:07	Weather Damp	
Date Cleaned 20150721			End Time 10:25	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C6-1									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
140.8 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	2		
266.7 ft.	Intruding Sealing Ring Loose/Poorly Fitting				5	<input type="checkbox"/>	12	12	2
276.5 ft.	Lining Failure Buckled					<input type="checkbox"/>	1		3
300.2 ft.	Water Level				5	<input type="checkbox"/>			
303.5 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C5-14									




Image Report 4/Page

Pipe Segment Refere... C6-1_C5-14	City Oliver Springs	Street Cherokee Place	Material PolyVinyl Chloride		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH C6-1	Total Length 303.5	Year Laid	Shape Circular		Location Details Apartment Complex	
DS Manhole C5-14	Length surveyed 303.5	Year Renewed	Height 8	Width 8	Pipe Joint... 13	



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C6-1



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 140.8 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 266.7 ft. Grade: 2
Condition: Intruding Sealing Ring Loose/Poorly Fitting
Remarks: N/A



Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C6-1_C5-14	Oliver Springs	Cherokee Place	PolyVinyl Chloride	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
C6-1	303.5		Circular	Apartment Complex	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
C5-14	303.5		8	8	13



Distance: 276.5 ft. Grade: 3
Condition: Lining Failure Buckled
Remarks: N/A



Distance: 300.2 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 303.5 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C5-14



Pipe Segment Refere... C6-1_C5-14	City Oliver Springs	Street Cherokee Place	Material PolyVinyl Chloride		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH C6-1	Total Length 303.5	Year Laid	Shape Circular		Location Details Apartment Complex	
DS Manhole C5-14	Length surveyed 303.5	Year Renewed	Height 8	Width 8	Pipe Joint... 13	
SPR 3	MPR 2	PO Number 4397-03		Customer GRW		
SPRI 3	MPRI 2	Work Order 4397-02		Purpose		
QSR 3100	QMR 2100			Pre-Rehabilitation Survey		
OPR 5	Surveyed By Barry_Rogers	Direction Downstream	Date 20150721		Media label	
OPRI 2.5	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 10:07		Weather Damp	
Date Cleaned 20150721			End Time 10:25		Additional Info	

Page #: 4