



## Defect Listing

Pipe Segment Refere... <b>C8-12_C8-11</b>	City <b>Oliver Springs</b>	Street <b>Dellwood Dr</b>	Material <b>PolyVinyl Chloride</b>	Location C... <b>Light High...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>C8-12</b>	Total Length <b>276.9</b>	Year Laid	Shape <b>Circular</b>	Location Details	
DS Manhole <b>C8-11</b>	Length surveyed <b>276.9</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>13</b>


SPR <b>N/A</b>	MPR <b>N/A</b>	PO Number <b>4397-03</b>		Customer <b>GRW</b>	
SPRI <b>N/A</b>	MPRI <b>N/A</b>	Work Order <b>4397-02</b>		Purpose <b>Pre-Rehabilitation Survey</b>	
QSR <b>N/A</b>	QMR <b>N/A</b>				
OPR <b>N/A</b>	Surveyed By <b>Barry Rogers</b>	Direction <b>Downstream</b>	Date <b>20150720</b>	Media label	
OPRI <b>N/A</b>	Certificate Number <b>U-1012-16405</b>	Pre-Cleaning <b>Jetting</b>	Time <b>09:24</b>	Weather <b>Dry</b>	
Date Cleaned <b>20150720</b>			End Time <b>09:45</b>	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C8-12									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
56.8 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
92.9 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
274.7 ft.	Water Level				5	<input type="checkbox"/>			
276.9 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C8-11									




## Image Report 4/Page

Pipe Segment Refere... <b>C8-12_C8-11</b>	<b>City</b> <b>Oliver Springs</b>	<b>Street</b> <b>Dellwood Dr</b>	<b>Material</b> <b>PolyVinyl Chloride</b>		<b>Location C...</b> <b>Light High...</b>	<b>Sewer Use</b> <b>Sanitary</b>
<b>Upstream MH</b> <b>C8-12</b>	Total Length <b>276.9</b>	Year Laid	<b>Shape</b> <b>Circular</b>		Location Details	
<b>DS Manhole</b> <b>C8-11</b>	<b>Length surveyed</b> <b>276.9</b>	Year Renewed	<b>Height</b> <b>8</b>	Width <b>8</b>	Pipe Joint... <b>13</b>	




Distance: 0.0 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: C8-12



Distance: 0.0 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 56.8 ft. Grade: 0  
Condition: Tap Factory Made  
Remarks: N/A




Distance: 92.9 ft. Grade: 0  
Condition: Tap Factory Made  
Remarks: N/A




## Image Report 4/Page

Pipe Segment Refere... <b>C8-12_C8-11</b>	<b>City</b> <b>Oliver Springs</b>	<b>Street</b> <b>Dellwood Dr</b>	<b>Material</b> <b>PolyVinyl Chloride</b>		<b>Location C...</b> <b>Light High...</b>	<b>Sewer Use</b> <b>Sanitary</b>
<b>Upstream MH</b> <b>C8-12</b>	Total Length <b>276.9</b>	Year Laid	<b>Shape</b> <b>Circular</b>		Location Details	
<b>DS Manhole</b> <b>C8-11</b>	<b>Length surveyed</b> <b>276.9</b>	Year Renewed	<b>Height</b> <b>8</b>	Width <b>8</b>	Pipe Joint... <b>13</b>	



Distance: 274.7 ft.      Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 276.9 ft.      Grade: 0  
Condition: Access Point Manhole  
Remarks: C8-11

## PACP Conditions

Pipe Segment Refere... C8-12_C8-11	City Oliver Springs	Street Dellwood Dr	Material PolyVinyl Chloride		Location C... Light High...	Sewer Use Sanitary
Upstream MH C8-12	Total Length 276.9	Year Laid	Shape Circular		Location Details	
DS Manhole C8-11	Length surveyed 276.9	Year Renewed	Height 8	Width 8	Pipe Joint... 13	
SPR N/A	MPR N/A	PO Number 4397-03			Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02			Purpose	
QSR N/A	QMR N/A				Pre-Rehabilitation Survey	
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150720		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 09:24		Weather Dry	
Date Cleaned 20150720			End Time 09:45		Additional Info	

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
<div>Continuous Defects</div> <div>CodeIDLength</div>			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Subtotals			0		Subtotals	0		Subtotals	0		
SUMMARY			Pipe Rating	0	Pipe Rating	0	Overall Pipe Rating	0			
			Structural Index	0	O&M Index	0	Overall Index	0			
			Str. Quick Rating	0000	O&M Quick Rating	0000	Ovrl. Quick Rating	0000			