



Defect Listing

Pipe Segment Refere... C8-6_C8-5	City Oliver Springs	Street Hermitage Dr	Material Fibreglass Reinforc...	Location C... Light High...	Sewer Use Sanitary
Upstream MH C8-6	Total Length 118.8	Year Laid	Shape Circular	Location Details	
DS Manhole C8-5	Length surveyed 118.8	Year Renewed	Height 8	Width 8	Pipe Joint... N/A


SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150720	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 14:21	Weather Light Rain	
Date Cleaned 20150720			End Time 14:31	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C8-6									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
88.9 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
116.7 ft.	Water Level				5	<input type="checkbox"/>			
118.8 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C8-5									




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C8-6_C8-5	Oliver Springs	Hermitage Dr	Fibreglass Reinforc...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
C8-6	118.8		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
C8-5	118.8		8	8	N/A



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C8-6



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 88.9 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 116.7 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C8-6_C8-5	Oliver Springs	Hermitage Dr	Fibreglass Reinforc...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
C8-6	118.8		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
C8-5	118.8		8	8	N/A



Distance: 118.8 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C8-5



Pipe Segment Refere... C8-6_C8-5	City Oliver Springs	Street Hermitage Dr	Material Fibreglass Reinforc...		Location C... Light High...	Sewer Use Sanitary
Upstream MH C8-6	Total Length 118.8	Year Laid	Shape Circular		Location Details	
DS Manhole C8-5	Length surveyed 118.8	Year Renewed	Height 8	Width 8	Pipe Joint... N/A	
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose		
QSR N/A	QMR N/A			Pre-Rehabilitation Survey		
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150720		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 14:21		Weather Light Rain	
Date Cleaned 20150720			End Time 14:31		Additional Info	

Page #: 4