



Defect Listing

Pipe Segment Refere... C8-8_C8-7	City Oliver Springs	Street HermitageDr	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH C8-8	Total Length 208.3	Year Laid	Shape Circular	Location Details	
DS Manhole C8-7	Length surveyed 208.3	Year Renewed	Height 8	Width 8	Pipe Joint... 4

SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150720	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 13:44	Weather Dry	
Date Cleaned 20150720			End Time 13:56	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C8-8									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
205.1 ft.	Water Level				5	<input type="checkbox"/>			
208.3 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: C8-7									




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
C8-8_C8-7	Oliver Springs	HermitageDr	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
C8-8	208.3		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
C8-7	208.3		8	8	4



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C8-8



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 205.1 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 208.3 ft. Grade: 0
Condition: Access Point Manhole
Remarks: C8-7



PACP Conditions

Pipe Segment Refere... C8-8_C8-7	City Oliver Springs	Street HermitageDr	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH C8-8	Total Length 208.3	Year Laid	Shape Circular	Location Details	
DS Manhole C8-7	Length surveyed 208.3	Year Renewed	Height 8	Width 8	Pipe Joint... 4
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A	Direction Downstream		Date 20150720	
OPR N/A	Surveyed By Barry_Rogers	Pre-Cleaning Jetting		Media label	
OPRI N/A	Certificate Number U-1012-16405	Time 13:44		Weather Dry	
Date Cleaned 20150720			End Time 13:56		Additional Info

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continuous Defects											
Code	ID	Length									
									</		