



Defect Listing

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D-16_D-15	Oliver Springs	Midway Dr	Fibreglass Reinforc...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
D-16	263		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
D-15	263		10	10	N/A


SPR	3	MPR	N/A	PO Number	Customer
SPRI	3	MPRI	N/A	4397-03	GRW
QSR	3100	QMR	N/A	Work Order	Purpose
				4397-02	Pre-Rehabilitation Survey
OPR	3	Surveyed By	Direction	Date	Media label
		Barry Rogers	Downstream	20150703	
OPRI	3	Certificate Number	Pre-Cleaning	Time	Weather
		U-1012-16405	Jetting	08:29	Damp
		Date Cleaned	End Time	Additional Info	
		20150703	08:43		

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D-16									
0.0 ft.	Water Level				10	<input type="checkbox"/>			
33.5 ft.	Lining Failure Wrinkled					<input type="checkbox"/>	11	1	3
Remarks: cont. defect									
76.0 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	10		
82.3 ft.	Water Level				35	<input type="checkbox"/>			
87.6 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
137.3 ft.	Water Level				40	<input type="checkbox"/>			
263.0 ft.	Water Level				5	<input type="checkbox"/>			
263.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D-15									




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D-16_D-15	Oliver Springs	Midway Dr	Fibreglass Reinforc...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
D-16	263		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
D-15	263		10	10	N/A




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D-16



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 33.5 ft. Grade: 3
Condition: Lining Failure Wrinkled
Remarks: cont. defect




Distance: 76.0 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D-16_D-15	Oliver Springs	Midway Dr	Fibreglass Reinforc...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
D-16	263		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
D-15	263		10	10	N/A




Distance: 82.3 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 87.6 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 137.3 ft. Grade: 0
Condition: Water Level
Remarks: N/A




Distance: 263.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D-16_D-15	Oliver Springs	Midway Dr	Fibreglass Reinforc...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
D-16	263		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
D-15	263		10	10	N/A



Distance: 263.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D-15



PACP Conditions

Pipe Segment Refere... D-16_D-15	City Oliver Springs	Street Midway Dr	Material Fibreglass Reinforc...	Location C... Light High...	Sewer Use Sanitary
Upstream MH D-16	Total Length 263	Year Laid	Shape Circular	Location Details	
DS Manhole D-15	Length surveyed 263	Year Renewed	Height 10	Width 10	Pipe Joint... N/A
SPR 3	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI 3	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR 3100	QMR N/A	Direction Downstream		Date 20150703	
OPR 3	Surveyed By Barry Rogers	Pre-Cleaning Jetting		Media label	
OPRI 3	Certificate Number U-1012-16405	Time 08:29		Weather Damp	
Date Cleaned 20150703			End Time 08:43		Additional Info

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	1	3	3	0	0	3	1	3
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continuous Defects											
Code	ID	Length									