



Defect Listing

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use
D-20_D-19		Oliver Springs		Oliver St	Ot	Other		Sanitary
Upstream MH		Total Length		Year Laid	Sh	Shape		Details
D-	D-20		2.1		Circ	ular		
DS Ma	DS Manhole		surveyed	Year Renewed	Year Renewed Height		Pipe Joint	
D-	D-19		2.1		8	8	N/A	
SPR	N/A	MPR	4	PO Number 4397-03		Customer		
0001	-	MBDI						
SPRI	N/A	MPRI	2	Work Order		Pre-F		
QSR	N/A	QMR	2200	4397-02				urvey
Ol	PR	Surveyed By		Direction	Date		Media label	
4	4	Barry_Rogers		Downstream	20150625			
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather	
:	2		2-16405	Jetting	14:45		Dry	
		Date C	leaned		End Time		Additional Info	
		2015	0625		14:49			

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Crada
	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	D-20								
0.0 ft.	Water Level				10				
36.4 ft.	Water Level Sag				20				2
70.6 ft.	Water Level Sag				25				2
111.6 ft.	Water Level				5				
112.1 ft.	Access Point Manhole				0				
Remarks:	D-19	•							





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
D-20_D-19	Oliver Springs	Oliver St	Other		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
D-20	112.1		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
D-19	112.1		8	8	N/A	,



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: D-20



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 36.4 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 70.6 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
D-20_D-19	Oliver Springs	Oliver St	Other		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
D-20	112.1		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
D-19	112.1		8	8	N/A	,



Distance: 111.6 ft. Grade:

Condition: Water Level

Remarks: N/A



Distance: 112.1 ft. Grade: 0

Condition: Access Point Manhole

Remarks: D-19



PACP Conditions

Pipe Segment Refere		City		Street	Mat	erial	Location C	Sewer Use	
D-20	D-20_D-19		Springs	Oliver St	Other		Light High	Sanitary	
Upstream MH Total Length		Length	Year Laid	Shape		Location Details			
D-20		112.1			Circular				
DS M	anhole	Length surveyed Year Renewed Height		Height	Width	Pipe Joint			
D-	D-19		2.1		8	8	N/A		
SPR	N/A	MPR	4	PO Number 4397-03 Work Order			Customer		
ODDI	NI/A	MPDI				GRW			
SPRI	N/A	MPRI	2			Purpose			
QSR	N/A	QMR	2200	4397-02	Pre-		Rehabilitation Survey		
Ol	PR	Surve	yed By	Direction	Date		Media label		
	4	Barry_Rogers		Downstream	20150625				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
:	2 U-1012-16405		Jetting	14:45		Dry			
		Date C	leaned		End Time		Additio	Additional Info	
		2015	0625	14:49					

	Structural Ratings			0	& M Ratin	gs	Con	nbined Ra	tings
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
	1	0	0	1	0	0	1	0	0
	2	0	0	2	2	4	2	2	4
	3	0	0	3	0	0	3	0	0
	4	0	0	4	0	0	4	0	0
	5	0	0	5	0	0	5	0	0
Continuous Defects Code ID Length									
	Subtotals	0		Subtotals	2		Subtotals	2	
SUMMARY	Struct	pe Rating ural Index ick Rating	0 0 0000	0	pe Rating &M Index	4 2.0 2200	Overall Pipe Rating Overall Index Ovrl. Quick Rating		4 2.0 2200