



## Defect Listing

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
<b>D-25_D-24</b>	<b>Oliver Springs</b>	<b>Oliver Dr</b>	<b>Concrete Pipe (non-...</b>	<b>Light High...</b>	<b>Sanitary</b>
Upstream MH	Total Length	Year Laid	Shape	Location Details	
<b>D-25</b>	<b>305.4</b>		<b>Circular</b>		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
<b>D-24</b>	<b>305.4</b>		<b>8</b>	<b>8</b>	<b>4</b>


SPR	N/A	MPR	2	PO Number	Customer
SPRI	N/A	MPRI	2	<b>4397-03</b>	<b>GRW</b>
QSR	N/A	QMR	2100	Work Order	Purpose
				<b>4397-02</b>	<b>Pre-Rehabilitation Survey</b>
OPR	Surveyed By	Direction	Date	Media label	
<b>2</b>	<b>Barry Rogers</b>	<b>Downstream</b>	<b>20150623</b>		
OPRI	Certificate Number	Pre-Cleaning	Time	Weather	
<b>2</b>	<b>U-1012-16405</b>	<b>Jetting</b>	<b>14:59</b>	<b>Dry</b>	
Date Cleaned			End Time	Additional Info	
<b>20150623</b>			<b>15:09</b>		

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D-25									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
38.8 ft.	Tap Saddle		6		0	<input type="checkbox"/>	3		
102.2 ft.	Water Level Sag				15	<input type="checkbox"/>			2
128.2 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
287.8 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
305.4 ft.	Water Level				5	<input type="checkbox"/>			
305.4 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D-24									




## Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D-25_D-24	Oliver Springs	Oliver Dr	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
D-25	305.4		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
D-24	305.4		8	8	4



Distance: 0.0 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: D-25



Distance: 0.0 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 38.8 ft. Grade: 0  
Condition: Tap Saddle  
Remarks: N/A



Distance: 102.2 ft. Grade: 2  
Condition: Water Level Sag  
Remarks: N/A






## Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D-25_D-24	Oliver Springs	Oliver Dr	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
D-25	305.4		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
D-24	305.4		8	8	4




Distance: 128.2 ft. Grade: 0  
Condition: Tap Factory Made  
Remarks: N/A



Distance: 287.8 ft. Grade: 0  
Condition: Tap Factory Made  
Remarks: N/A



Distance: 305.4 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 305.4 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: D-24



## Albuquerque, NM

SPR	N/A	MPR	2	PO Number		Customer			
SPRI	N/A	MPRI	2	4397-03		GRW			
QSR	N/A	QMR	2100	Work Order		Purpose			
				4397-02		Pre-Rehabilitation Survey			
OPR		Surveyed By		Direction		Date		Media label	
2		Barry_Rogers		Downstream		20150623			
OPRI		Certificate Number		Pre-Cleaning		Time		Weather	
2		U-1012-16405		Jetting		14:59		Dry	
Date Cleaned				End Time		Additional Info			
20150623				15:09					

Page 1 of 1