



## Defect Listing

Pipe Segment Refere... <b>D1-7A_D1-7</b>	City <b>Oliver Springs</b>	Street <b>Bennett Rd</b>	Material <b>Concrete Pipe (non-...</b>	Location C... <b>Light High...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>D1-7A</b>	Total Length <b>202.3</b>	Year Laid	Shape <b>Circular</b>	Location Details <b>208 Bennet Rd</b>	
DS Manhole <b>D1-7</b>	Length surveyed <b>202.3</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>4</b>


SPR <b>N/A</b>	MPR <b>N/A</b>	PO Number <b>4397-03</b>	Customer <b>GRW</b>
SPRI <b>N/A</b>	MPRI <b>N/A</b>	Work Order <b>4397-02</b>	Purpose <b>Pre-Rehabilitation Survey</b>
QSR <b>N/A</b>	QMR <b>N/A</b>		
OPR <b>N/A</b>	Surveyed By <b>Barry Rogers</b>	Direction <b>Downstream</b>	Date <b>20150708</b>
OPRI <b>N/A</b>	Certificate Number <b>U-1012-16405</b>	Pre-Cleaning <b>Jetting</b>	Time <b>12:28</b>
	Date Cleaned <b>20150708</b>	End Time <b>12:35</b>	Weather <b>Damp</b>
			Media label
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D1-7A									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
202.3 ft.	Water Level				5	<input type="checkbox"/>			
202.3 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D1-7									




## Image Report 4/Page

Pipe Segment Refere... <b>D1-7A_D1-7</b>	<b>City</b> <b>Oliver Springs</b>	<b>Street</b> <b>Bennett Rd</b>	<b>Material</b> <b>Concrete Pipe (non-...</b>		<b>Location C...</b> <b>Light High...</b>	<b>Sewer Use</b> <b>Sanitary</b>
<b>Upstream MH</b> <b>D1-7A</b>	Total Length <b>202.3</b>	Year Laid	<b>Shape</b> <b>Circular</b>		Location Details <b>208 Bennet Rd</b>	
<b>DS Manhole</b> <b>D1-7</b>	<b>Length surveyed</b> <b>202.3</b>	Year Renewed	<b>Height</b> <b>8</b>	Width <b>8</b>	Pipe Joint...	



Distance: 0.0 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: D1-7A



Distance: 0.0 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 202.3 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 202.3 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: D1-7



Pipe Segment Refere... D1-7A_D1-7	City Oliver Springs	Street Bennett Rd	Material Concrete Pipe (non-...		Location C... Light High...	Sewer Use Sanitary
Upstream MH D1-7A	Total Length 202.3	Year Laid	Shape Circular		Location Details 208 Bennet Rd	
DS Manhole D1-7	Length surveyed 202.3	Year Renewed	Height 8	Width 8	Pipe Joint...	
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose		
QSR N/A	QMR N/A			Pre-Rehabilitation Survey		
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150708		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 12:28		Weather Damp	
Date Cleaned 20150708			End Time 12:35		Additional Info	

Page #: 3