



Defect Listing

Pipe Segment Refere... D11-14_D11-13	City Oliver Springs	Street England Dr	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH D11-14	Total Length 315.2	Year Laid	Shape Circular	Location Details England Dr	
DS Manhole D11-13	Length surveyed 1.4	Year Renewed	Height 8	Width 8	Pipe Joint... 4


SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Upstream	Date 20150622	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning No Pre-Cleaning	Time 11:45	Weather Damp	
Date Cleaned			End Time 11:47	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D11-13									
0.0 ft.	Water Level				10	<input type="checkbox"/>			
1.4 ft.	Survey Abandoned				0	<input type="checkbox"/>			
Remarks: Line full of Debris unable to clean									



Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D11-14_D11-13	Oliver Springs	England Dr	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
D11-14	315.2		Circular	England Dr	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
D11-13	1.4		8	8	4



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D11-13



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 1.4 ft. Grade: 0
Condition: Survey Abandoned
Remarks: Line full of Debris unable to clean



PACP Conditions

Pipe Segment Refere... D11-14_D11-13	City Oliver Springs	Street England Dr	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH D11-14	Total Length 315.2	Year Laid	Shape Circular	Location Details England Dr	
DS Manhole D11-13	Length surveyed 1.4	Year Renewed	Height 8	Width 8	Pipe Joint... 4
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A	Direction Upstream		Date 20150622	
OPR N/A	Surveyed By Barry Rogers	Pre-Cleaning No Pre-Cleaning		Media label	
OPRI N/A	Certificate Number U-1012-16405	Time 11:45		Weather Damp	
Date Cleaned			End Time 11:47		Additional Info

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code	ID	Length									