



Defect Listing

Pipe Segment Refere... D11-2_D11-1	City Oliver Springs	Street Airport Rd	Material Other	Location C... Light High...	Sewer Use Sanitary
Upstream MH D11-2	Total Length 322	Year Laid	Shape Circular	Location Details	
DS Manhole D11-1	Length surveyed 322	Year Renewed	Height 8	Width 8	Pipe Joint... N/A


SPR N/A	MPR 6	PO Number 4397-03	Customer GRW
SPRI N/A	MPRI 2	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR N/A	QMR 2300		
OPR 6	Surveyed By Barry Rogers	Direction Downstream	Date 20150701
OPRI 2	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 10:18
	Date Cleaned 20150701	End Time 10:29	Weather Saturated
			Media label
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D11-2									
0.0 ft.	Water Level				10	<input type="checkbox"/>			
64.4 ft.	Tap Break-In Intruding		6	1	0	<input type="checkbox"/>	3		2
217.6 ft.	Water Level Sag				15	<input type="checkbox"/>			2
317.3 ft.	Water Level Sag				25	<input type="checkbox"/>			2
322.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D11-1									




Image Report 4/Page


Pipe Segment Refere... D11-2_D11-1	City Oliver Springs	Street Airport Rd	Material Other		Location C... Light High...	Sewer Use Sanitary
Upstream MH D11-2	Total Length 322	Year Laid	Shape Circular		Location Details	
DS Manhole D11-1	Length surveyed 322	Year Renewed	Height 8	Width 8	Pipe Joint...	N/A



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D11-2



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 64.4 ft. Grade: 2
Condition: Tap Break-In Intruding
Remarks: N/A



Distance: 217.6 ft. Grade: 2
Condition: Water Level Sag
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere... D11-2_D11-1	City Oliver Springs	Street Airport Rd	Material Other	Location C... Light High...	Sewer Use Sanitary
Upstream MH D11-2	Total Length 322	Year Laid	Shape Circular	Location Details	
DS Manhole D11-1	Length surveyed 322	Year Renewed	Height 8	Width 8	Pipe Joint... N/A



Distance: 317.3 ft. Grade: 2
Condition: Water Level Sag
Remarks: N/A



Distance: 322.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D11-1



PACP Conditions

Pipe Segment Refere... D11-2_D11-1	City Oliver Springs	Street Airport Rd	Material Other		Location C... Light High...	Sewer Use Sanitary
Upstream MH D11-2	Total Length 322	Year Laid	Shape Circular		Location Details	
DS Manhole D11-1	Length surveyed 322	Year Renewed	Height 8	Width 8	Pipe Joint... N/A	
SPR N/A	MPR 6	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI 2	Work Order 4397-02		Purpose Pre-Rehabilitation Survey		
QSR N/A	QMR 2300					
OPR 6	Surveyed By Barry_Rogers	Direction Downstream	Date 20150701		Media label	
OPRI 2	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 10:18		Weather Saturated	
Date Cleaned 20150701			End Time 10:29		Additional Info	

[illegible]