



## Defect Listing

Pipe Segment Refere... <b>D11-2B_D11-2A</b>	City <b>Oliver Springs</b>	Street <b>Airport Rd</b>	Material <b>Other</b>	Location C... <b>Light High...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>D11-2B</b>	Total Length <b>81.3</b>	Year Laid	Shape <b>Circular</b>	Location Details	
DS Manhole <b>D11-2A</b>	Length surveyed <b>81.3</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>N/A</b>

SPR <b>N/A</b>	MPR <b>N/A</b>	PO Number <b>4397-03</b>		Customer <b>GRW</b>	
SPRI <b>N/A</b>	MPRI <b>N/A</b>	Work Order <b>4397-02</b>		Purpose <b>Pre-Rehabilitation Survey</b>	
QSR <b>N/A</b>	QMR <b>N/A</b>				
OPR <b>N/A</b>	Surveyed By <b>Barry Rogers</b>	Direction <b>Downstream</b>	Date <b>20150701</b>	Media label	
OPRI <b>N/A</b>	Certificate Number <b>U-1012-16405</b>	Pre-Cleaning <b>Jetting</b>	Time <b>09:11</b>	Weather <b>Saturated</b>	
Date Cleaned <b>20150701</b>			End Time <b>09:14</b>	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D11-2B									
0.0 ft.	Water Level				20	<input type="checkbox"/>			
77.3 ft.	Water Level				5	<input type="checkbox"/>			
81.3 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D11-2A									



## Image Report 4/Page


Pipe Segment Refere... <b>D11-2B_D11-2A</b>	City <b>Oliver Springs</b>	Street <b>Airport Rd</b>	Material <b>Other</b>	Location C... <b>Light High...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>D11-2B</b>	Total Length <b>81.3</b>	Year Laid	Shape <b>Circular</b>	Location Details	
DS Manhole <b>D11-2A</b>	Length surveyed <b>81.3</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>N/A</b>



Distance: 0.0 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: D11-2B



Distance: 0.0 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 77.3 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 81.3 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: D11-2A



## PACP Conditions

Pipe Segment Refere... D11-2B_D11-2A	City Oliver Springs	Street Airport Rd	Material Other		Location C... Light High...	Sewer Use Sanitary
Upstream MH D11-2B	Total Length 81.3	Year Laid	Shape Circular		Location Details	
DS Manhole D11-2A	Length surveyed 81.3	Year Renewed	Height 8	Width 8	Pipe Joint... N/A	
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose		
QSR N/A	QMR N/A			Pre-Rehabilitation Survey		
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150701		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 09:11		Weather Saturated	
Date Cleaned 20150701			End Time 09:14		Additional Info	

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
<div>Continuous Defects</div> <div><div>Code</div><div>ID</div><div>Length</div></div> <div></div> <div></div>			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
			Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY			Pipe Rating	0		Pipe Rating	0		Overall Pipe Rating	0	
			Structural Index	0		O&M Index	0		Overall Index	0	
			Str. Quick Rating	0000		O&M Quick Rating	0000		Ovrl. Quick Rating	0000	