



Defect Listing

Pipe Segment Refere... D14-2_D14-1	City Oliver Springs	Street First Norway	Material Concrete Pipe (non-...	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH D14-2	Total Length 176.6	Year Laid	Shape Circular	Location Details	
DS Manhole D14-1	Length surveyed 176.6	Year Renewed	Height 8	Width 8	Pipe Joint... 4

SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150623	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 10:02	Weather Very Dry	
Date Cleaned 20150623			End Time 10:11	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D14-2									
0.0 ft.	Water Level				0	<input type="checkbox"/>			
106.3 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
175.3 ft.	Water Level				0	<input type="checkbox"/>			
176.6 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D14-1									




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D14-2_D14-1	Oliver Springs	First Norway	Concrete Pipe (non-...	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
D14-2	176.6		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
D14-1	176.6		8	8	4



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D14-2



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 106.3 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 175.3 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D14-2 D14-1	Oliver Springs	First Norway	Concrete Pipe (non-...	Easement/R...	Sanitary
Upstream MH D14-2	Total Length 176.6	Year Laid	Shape Circular	Location Details	
DS Manhole D14-1	Length surveyed 176.6	Year Renewed	Height 8	Width 8	Pipe Joint... 4



Distance: 176.6 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D14-1



Pipe Segment Refere... D14-2_D14-1	City Oliver Springs	Street First Norway	Material Concrete Pipe (non-...		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH D14-2	Total Length 176.6	Year Laid	Shape Circular		Location Details	
DS Manhole D14-1	Length surveyed 176.6	Year Renewed	Height 8	Width 8	Pipe Joint... 4	
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose		
QSR N/A	QMR N/A			Pre-Rehabilitation Survey		
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150623		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 10:02		Weather Very Dry	
Date Cleaned 20150623			End Time 10:11		Additional Info	

Page #: 4