



Defect Listing

Pipe Segment Refere... D16-3_D16-2	City Oliver Springs	Street First Norway Ln	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH D16-3	Total Length 207.5	Year Laid	Shape Circular	Location Details	
DS Manhole D16-2	Length surveyed 207.5	Year Renewed	Height 8	Width 8	Pipe Joint... 4

SPR 1	MPR N/A	PO Number 4397-03	Customer GRW
SPRI 1	MPRI N/A	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR 1100	QMR N/A		
OPR 1	Surveyed By Barry Rogers	Direction Downstream	Date 20150626
OPRI 1	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 08:05
	Date Cleaned 20150626	End Time 08:17	Weather Dry
		Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
▲ 0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D16-1									
▲ 0.0 ft.	Water Level				5	<input type="checkbox"/>			
▲ 3.0 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3	3	
▲ 27.4 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9	9	
▲ 73.6 ft.	Joint Offset Medium				0	<input type="checkbox"/>			1
▲ 109.4 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9	9	
▲ 116.2 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3	3	
▲ 204.1 ft.	Water Level				5	<input type="checkbox"/>			
▲ 207.5 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D16-2									




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D16-3_D16-2	Oliver Springs	First Norway Ln	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH D16-3	Total Length 207.5	Year Laid	Shape Circular	Location Details	
DS Manhole D16-2	Length surveyed 207.5	Year Renewed	Height 8	Width 8	Pipe Joint... 4



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D16-1



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 3.0 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 27.4 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D16-3_D16-2	Oliver Springs	First Norway Ln	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH D16-3	Total Length 207.5	Year Laid	Shape Circular	Location Details	
DS Manhole D16-2	Length surveyed 207.5	Year Renewed	Height 8	Width 8	Pipe Joint... 4




Distance: 73.6 ft. Grade: 1
Condition: Joint Offset Medium
Remarks: N/A



Distance: 109.4 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 116.2 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Distance: 204.1 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D16-3_D16-2	Oliver Springs	First Norway Ln	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH D16-3	Total Length 207.5	Year Laid	Shape Circular	Location Details	
DS Manhole D16-2	Length surveyed 207.5	Year Renewed	Height 8	Width 8	Pipe Joint... 4



Distance: 207.5 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D16-2



PACP Conditions

Pipe Segment Refere... D16-3_D16-2	City Oliver Springs	Street First Norway Ln	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH D16-3	Total Length 207.5	Year Laid	Shape Circular	Location Details	
DS Manhole D16-2	Length surveyed 207.5	Year Renewed	Height 8	Width 8	Pipe Joint... 4
SPR 1	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI 1	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR 1100	QMR N/A	Direction Downstream		Date 20150626	
OPR 1	Surveyed By Barry Rogers	Pre-Cleaning Jetting		Media label	
OPRI 1	Certificate Number U-1012-16405	Time 08:05		Weather Dry	
Date Cleaned 20150626			End Time 08:17		Additional Info

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
			1	1	1	1	0	0	1	1	1
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continuous Defects											
Code	ID	Length									
			Subtotals	1		Subtotals	0		Subtotals	1	
SUMMARY			Pipe Rating	1		Pipe Rating	0		Overall Pipe Rating	1	
			Structural Index	1.0		O&M Index	0		Overall Index	1.0	
			Str. Quick Rating	1100		O&M Quick Rating	0000		Ovrl. Quick Rating	1100	