



Defect Listing

Pipe Segment Refere... D17-1_D16-1	City Oliver Springs	Street Wall ST	Material Concrete Pipe (non-...	Location C... Yard	Sewer Use Sanitary
Upstream MH D17-1	Total Length 351	Year Laid	Shape Circular	Location Details	
DS Manhole D16-1	Length surveyed 351	Year Renewed	Height 8	Width 8	Pipe Joint... 4

SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150625	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 15:36	Weather Dry	
Date Cleaned 20150625			End Time 15:50	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D17-1									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
128.8 ft.	Tap Factory Made Active		6		0	<input type="checkbox"/>	3		
346.8 ft.	Water Level				5	<input type="checkbox"/>			
351.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: D16-1									




Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D17-1_D16-1	Oliver Springs	Wall ST	Concrete Pipe (non-...	Yard	Sanitary
Upstream MH D17-1	Total Length 351	Year Laid	Shape Circular	Location Details	
DS Manhole D16-1	Length surveyed 351	Year Renewed	Height 8	Width 8	Pipe Joint... 4




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D17-1



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 128.8 ft. Grade: 0
Condition: Tap Factory Made Active
Remarks: N/A



Distance: 346.8 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
D17-1_D16-1	Oliver Springs	Wall ST	Concrete Pipe (non-...	Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
D17-1	351		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
D16-1	351		8	8	4



Distance: 351.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: D16-1



Pipe Segment Refere... D17-1_D16-1	City Oliver Springs	Street Wall ST	Material Concrete Pipe (non-...		Location C... Yard	Sewer Use Sanitary
Upstream MH D17-1	Total Length 351	Year Laid	Shape Circular		Location Details	
DS Manhole D16-1	Length surveyed 351	Year Renewed	Height 8	Width 8	Pipe Joint... 4	
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose		
QSR N/A	QMR N/A			Pre-Rehabilitation Survey		
OPR N/A	Surveyed By Barry_Rogers	Direction Downstream	Date 20150625		Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 15:36		Weather Dry	
Date Cleaned 20150625			End Time 15:50		Additional Info	

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code	ID	Length									